

Register entry, as of 28 October 2026

Listed for sale

Record ID 8d927ba44dfa

2019 Toyota 4-Runner SR5/SR5 Premium/TRD Off Road/TRD Off Road Premium/Ltd/Ltd Night Shade/TRD Pro

4.0 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTE BU5JR 5 K 5 637054

WMI 1-3

Toyota Motor Corporation

DESCRIPTOR 4-8

4-Runner · 4.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Tahara

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	4.0 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	4-Runner	Drive	4WD
Trim	SR5/SR5 Premium/TRD Off Road/TRD Off Road Premium/Ltd/Ltd Night Shade/TRD Pro	Maker	TOYOTA MOTOR CORPORATION
Body	Sport Utility Vehicle	Plant	Tahara, Aichi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/4-runner/2019

2 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.



Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.

Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.

www.toyota.ca/en/owners/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$44,995^[5], \$4,095 over the median of \$40,900^[4].



Lowest ask	\$31,910
Middle half	\$37,944 – \$43,974
Median ask	\$40,900
This car	\$44,995

Same configuration · 31 live listings · as of 28 Oct 2026

OTHER 2019 TOYOTA 4-RUNNER LISTINGS [5]

Saint John, NB · 135,434 km	\$36,295
Newmarket, ON · 95,124 km	\$43,999
Newmarket, ON · 112,008 km	\$43,900
Calgary, AB · 146,399 km	\$40,721
Cranbrook, BC · 135,054 km	\$46,479
Barrie, ON · 120,600 km	\$48,888

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Tahara, Aichi, Japan
28 Oct 2020	Transport Canada recall 2020514 ^[2] Issued for the model year · Fuel system
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Edson, AB ^[5] Bannister Ford Edson · asking \$44,995
28 Oct 2026	Listing last updated ^[5] asking \$44,995



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 31 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

