

Register entry, as of 29 October 2026

Listed for sale

Record ID 079d82168be4

2013 Lexus ES 350

3.5 L, 6 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTH **BK1GG** **9** **D** **2** **031770**

WMI 1-3

Lexus · TOYOTA MOTOR C...

DESCRIPTOR 4-8

ES · 3.5 L

CHECK 9

Computes

YEAR 10

2013

PLANT 11

Miyawaka

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	3.5 L, 6 cylinders
Make	Lexus	Fuel	Gasoline
Model	ES	Drive	4x2
Trim	350	Maker	TOYOTA MOTOR CORPORATION
Body	Sedan	Plant	Miyawaka, Fukuoka, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/es/2013

3 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Lights and instruments

2020577 27 Nov 2020

Issue: On certain vehicles, the rear reflex reflectors may not have been manufactured correctly. As a result, the rear reflectors may reflect less light than what is required by Canadian regulations. Safety Risk: This small error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has made changes to ensure that all new vehicles have fully compliant rear reflex reflectors.



Brakes

2015521 3 Nov 2015

On certain vehicles equipped with Pre-Collision System (PCS), the system could unexpectedly activate while operating the vehicle. Under certain situations, the system may interpret a steel joint or plate in the roadway as an obstacle, and the system may apply the service brake automatically. If the PCS applies unexpected braking force during normal vehicle operation when no impending collision object is present, it could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will disable the Pre-Collision System (PCS) as an interim measure, and when parts become available, will replace the PCS components with improved parts.

Listed for the model year, not checked against your VIN. Lexus confirms which apply.


Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.

www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$19,999^[5], \$5,002 over the median of \$14,997^[4].



Lowest ask	\$11,999
Middle half	\$14,246 – \$15,487
Median ask	\$14,997
This car	\$19,999

Same model year · 4 live listings · as of 29 Oct 2026

OTHER 2013 LEXUS ES LISTINGS ^[5]

Montréal, QC · 104,423 km	\$16,200
Markham, ON · 175,848 km	\$14,995

§4 EVENTS

2013	Model year 2013 ^[1] Assembly plant Miyawaka, Fukuoka, Japan
3 Nov 2015	Transport Canada recall 2015521 ^[2] Issued for the model year · Brakes
27 Nov 2020	Transport Canada recall 2020577 ^[2] Issued for the model year · Lights and instruments
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
3 Mar 2026	Listed for sale, Edmonton, AB ^[5] Legend Auto Sales · asking \$19,999
26 Oct 2026	Listing last updated ^[5] asking \$19,999



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

