

Register entry, as of 28 October 2026

Listed for sale

Record ID fd10ec54407b

2018 Lexus LS 500

3.4 L, 6 cylinders · 4WD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTH C51FF 9 J 5 000310

WMI 1-3

Lexus · TOYOTA MOTOR C...

DESCRIPTOR 4-8

LS · 3.4 L

CHECK 9

Computes

YEAR 10

2018

PLANT 11

Tahara

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.4 L, 6 cylinders
Make	Lexus	Fuel	Gasoline
Model	LS	Drive	4WD
Trim	500	Maker	TOYOTA MOTOR CORPORATION
Body	Sedan	Plant	Tahara, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/ls/2018

4 recalls listed by Transport Canada for this model year

Seats and restraints

2024229 17 Apr 2024

Issue: On certain vehicles, the occupant classification system (OCS) may not work properly due to interference between seat components. As a result, the airbag system can turn off the passenger-front airbag even when a passenger is seated in the front passenger seat. Note: This recall only affects certain vehicles equipped with the Executive package. Safety Risk: An airbag system that does not work properly could increase the risk of injury in a crash. Corrective Actions: Lexus will notify owners by mail and advise you to take your vehicle to a dealership to inspect the front passenger seat. If interference is found, the dealer will adjust the seat as necessary, and re-calibrate the occupant classification system.

Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Fuel system

2020088 4 Mar 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recall SRC R95/SRC R96 (Transport Canada Recall No. 2020-005) Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.



Tires

2019097 27 Feb 2019

Issue: On certain vehicles, a crack could develop on the sidewall of the tire. Over time, the crack could expand and could lead to a partial tread separation. Safety Risk: A tire tread separation could affect vehicle stability and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer for an inspection of the tires. If the vehicle has one or more affected tires, all four tires will be replaced.

Listed for the model year, not checked against your VIN. Lexus confirms which apply.

Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.

www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$42,995^[5], \$10,000 under the median of \$52,995^[4].



Lowest ask	\$42,995
Middle half	\$50,292 – \$55,946
Median ask	\$52,995
This car	\$42,995

Same model year · 7 live listings · as of 28 Oct 2026

OTHER 2018 LEXUS LS LISTINGS [5]

Markham, ON · 138,940 km	\$45,500
Saint-Laurent, QC · 90,216 km	\$52,895
North Vancouver, BC · 79,002 km	\$52,995
Vancouver, BC · 79,002 km	\$52,995
North Vancouver, BC · 79,002 km	\$52,995
Vancouver, BC · 79,002 km	\$52,995

§4 EVENTS

2018	Model year 2018 ^[1] Assembly plant Tahara, Japan
27 Feb 2019	Transport Canada recall 2019097 ^[2] Issued for the model year · Tires
4 Mar 2020	Transport Canada recall 2020088 ^[2] Issued for the model year · Fuel system
28 Oct 2020	Transport Canada recall 2020514 ^[2] Issued for the model year · Fuel system
17 Apr 2024	Transport Canada recall 2024229 ^[2] Issued for the model year · Seats and restraints



26 Oct 2026 Listed for sale, Markham, ON^[5]
Don Valley North Lexus · asking \$42,995

28 Oct 2026 Listing last updated^[5]
asking \$42,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 7 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

