Register entry, as of 27 October 2026 Listed for sale Record ID f454c2a161b6

2016 Lexus GS 350

3.5 L, 6 cylinders · 4WD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTH	CZ1BL	2	G	A	000858
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Lexus · TOYOTA MOTOR C…	GS · 3.5 L	Computes	2016	Toyota City	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	3.5 L, 6 cylinders
Make	Lexus	Fuel	Gasoline
Model	GS	Drive	4WD
Trim	350	Maker	TOYOTA MOTOR CORPORATION
Body	Sedan	Plant	Toyota City, Aichi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/gs/2016

5 recalls listed by Transport Canada for this model year

Fuel system

2026175 8 Apr 2026

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Lexus will notify owners by mail and advise you to take your vehicle to a dealer to replace the fuel pump.

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Lights and instruments

2020577 27 Nov 2020

Issue: On certain vehicles, the rear reflex reflectors may not have been manufactured correctly. As a result, the rear reflectors may reflect less light than what is required by Canadian regulations. Safety Risk: This small error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has made changes to ensure that all new vehicles have fully compliant rear reflex reflectors.

Fuel system

2018091 14 Feb 2018

On certain vehicles equipped with a 5.0L V8 gasoline engine, a fatigue crack could develop on the cover of the high pressure fuel pump. If the vehicle is operated with this condition, the crack could expand and allow fuel to leak. Leaking fuel in the presence of an ignition source could result in a fire, increasing the risk of injury and/or damage to property. Correction: Dealers will replace the high pressure fuel pumps with improved ones.

Electrical

2017363 20 Jul 2017

On certain vehicles, the electrical power cords of some dealer installed block heaters may have been improperly manufactured, causing the wires to contact each other, resulting in a short circuit. A short circuit could lead to a fire which would increase the risk of injury and/or damage to property. Correction: For vehicles where the subject block heater was approved for installation, the dealer will replace the block heater assembly with a new one of an improved design. For vehicles where the subject block heater was not approved for installation, dealers will remove the block heater assembly. In the interim, until the remedy can be performed, dealers will cut the plug end from the block heater cord to disable the block heater's operation.

> Listed for the model year, not checked against your VIN. Lexus confirms which apply.
> Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.
> www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $36,180[5], $5,680 over the median of $30,500[4].



Lowest ask	$24,995
Middle half	$26,999 – $36,180
Median ask	$30,500
This car	$36,180

Same model year · 5 live listings · as of 27 Oct 2026

OTHER 2016 LEXUS GS LISTINGS [5]

Milton, ON · 156,570 km	$24,995
Etobicoke, ON · 98,998 km	$26,999
Oakville, ON · 98,998 km	$26,999
Oakville, ON · 98,998 km	$26,999

§4 EVENTS

2016	Model year 2016[1] Assembly plant Toyota City, Aichi, Japan
20 Jul 2017	Transport Canada recall 2017363[2] Issued for the model year · Electrical
14 Feb 2018	Transport Canada recall 2018091[2] Issued for the model year · Fuel system

27 Nov 2020	Transport Canada recall 2020577[2] Issued for the model year · Lights and instruments
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
24 Nov 2025	Listed for sale, Oakville, ON[5] Medallion Motors Inc · asking $36,180
8 Apr 2026	Transport Canada recall 2026175[2] Issued for the model year · Fuel system
27 Oct 2026	Listing last updated[5] asking $36,180

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 5 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.