

Register entry, as of 27 October 2026

Listed for sale

Record ID c132f848e3b4

2016 Lexus NX 200t Luxury

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTJ BARBZ 2 G 2 074280

WMI 1-3

Lexus · TOYOTA MOTOR C...

DESCRIPTOR 4-8

NX · 2.0 L

CHECK 9

Computes

YEAR 10

2016

PLANT 11

Miyawaka

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	2.0 L, 4 cylinders
Make	Lexus	Fuel	Gasoline
Model	NX	Drive	4WD
Trim	200t Luxury	Maker	TOYOTA MOTOR CORPORATION
Body	Sport Utility Vehicle	Plant	Miyawaka, Fukuoka, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/nx/2016

3 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Airbag

2018061 31 Jan 2018

On certain vehicles, the airbag system pressure sensors and/or acceleration sensors used to detect vehicle impact may contain manufacturing defects. As a result, the airbag warning light may illuminate and the side/curtain shield airbags and/or front airbags may not deploy, increasing the risk of injury in the event of a crash. Correction: Dealers will inspect and replace the defective sensors as necessary. Note: This will not affect the front airbags of the Prius model.



Electrical

2017363 20 Jul 2017

On certain vehicles, the electrical power cords of some dealer installed block heaters may have been improperly manufactured, causing the wires to contact each other, resulting in a short circuit. A short circuit could lead to a fire which would increase the risk of injury and/or damage to property. Correction: For vehicles where the subject block heater was approved for installation, the dealer will replace the block heater assembly with a new one of an improved design. For vehicles where the subject block heater was not approved for installation, dealers will remove the block heater assembly. In the interim, until the remedy can be performed, dealers will cut the plug end from the block heater cord to disable the block heater's operation.

Listed for the model year, not checked against your VIN. Lexus confirms which apply.
Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.

www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$16,900^[5], \$4,585 under the median of \$21,485^[4].



Lowest ask	\$14,995
Middle half	\$18,480 – \$22,788
Median ask	\$21,485
This car	\$16,900

Same configuration · 13 live listings · as of 27 Oct 2026

OTHER 2016 LEXUS NX LISTINGS [5]

Halifax, NS · 96,393 km	\$22,788
North Vancouver, BC · 98,497 km	\$25,695
Richmond, BC · 109,506 km	\$24,995
North York, ON · 161,051 km	\$18,480
St. Catharines, ON · 187,324 km	\$19,900

§4 EVENTS

2016	Model year 2016 ^[1] Assembly plant Miyawaka, Fukuoka, Japan
20 Jul 2017	Transport Canada recall 2017363 ^[2] Issued for the model year · Electrical
31 Jan 2018	Transport Canada recall 2018061 ^[2] Issued for the model year · Airbag
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
7 Jul 2026	Listed for sale, Airdrie, AB ^[5] SJL Auto LTD · asking \$16,900



27 Oct 2026 Listing last updated^[5]
asking \$16,900

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 13 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

