

Register entry, as of 28 October 2026

Listed for sale

Record ID 0a7eca3c5518

# 2015 Lexus NX 200t Luxury

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**JTJ BARBZ 4 F 2 003841**

WMI 1-3

Lexus · TOYOTA MOTOR C...

DESCRIPTOR 4-8

NX · 2.0 L

CHECK 9

Computes

YEAR 10

2015

PLANT 11

Miyawaka

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                          |
|------------|-----------------------|--------|--------------------------|
| Model year | 2015                  | Engine | 2.0 L, 4 cylinders       |
| Make       | Lexus                 | Fuel   | Gasoline                 |
| Model      | NX                    | Drive  | 4WD                      |
| Trim       | 200t Luxury           | Maker  | TOYOTA MOTOR CORPORATION |
| Body       | Sport Utility Vehicle | Plant  | Miyawaka, Fukuoka, Japan |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/nx/2015

## 2 recalls listed by Transport Canada for this model year

### Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

### Airbag

2018061 31 Jan 2018

On certain vehicles, the airbag system pressure sensors and/or acceleration sensors used to detect vehicle impact may contain manufacturing defects. As a result, the airbag warning light may illuminate and the side/curtain shield airbags and/or front airbags may not deploy, increasing the risk of injury in the event of a crash. Correction: Dealers will inspect and replace the defective sensors as necessary. Note: This will not affect the front airbags of the Prius model.

Listed for the model year, not checked against your VIN. Lexus confirms which apply.

Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.

[www.lexus.ca/en/maintain-your-lexus/campaigns/](http://www.lexus.ca/en/maintain-your-lexus/campaigns/)



United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE <sup>[4]</sup>

This car asks \$16,950<sup>[5]</sup>, \$1,699 under the median of \$18,649<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$15,988            |
| Middle half | \$17,995 – \$21,365 |
| Median ask  | \$18,649            |
| This car    | \$16,950            |

Same configuration · 12 live listings · as of 28 Oct 2026

#### OTHER 2015 LEXUS NX LISTINGS <sup>[5]</sup>

|                              |          |
|------------------------------|----------|
| Kelowna, BC · 158,039 km     | \$22,495 |
| Mississauga, ON · 126,219 km | \$18,800 |
| Burnaby, BC · 136,300 km     | \$18,995 |
| Oakville, ON · 157,817 km    | \$17,995 |
| Kelowna, BC · 158,039 km     | \$22,495 |
| Guelph, ON · 156,017 km      | \$18,498 |

### §4 EVENTS

|             |                                                                                            |
|-------------|--------------------------------------------------------------------------------------------|
| 2015        | Model year 2015 <sup>[1]</sup><br>Assembly plant Miyawaka, Fukuoka, Japan                  |
| 31 Jan 2018 | Transport Canada recall 2018061 <sup>[2]</sup><br>Issued for the model year · Airbag       |
| 24 Nov 2021 | Transport Canada recall 2021723 <sup>[2]</sup><br>Issued for the model year · Electrical   |
| 26 Oct 2026 | Listed for sale, Notre-Dame-des-Prairies, QC <sup>[5]</sup><br>rdauto.ca · asking \$16,950 |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$16,950                                     |

### §5 DOCUMENTS

Window sticker      We have not collected this label yet.

#### SOURCES

|                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 12 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                     |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                  |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

