Register entry, as of 27 October 2026 Listed for sale Record ID 4914e8ce68c4

# 2024 Lexus GX GX 550

3.4 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| JTJ | TBCDX | X | R | 5 | 021290 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Lexus · TOYOTA MOTOR C… | GX · 3.4 L | Computes | 2024 | Tahara | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2024 | Engine | 3.4 L, 6 cylinders |
| Make | Lexus | Fuel | Gasoline |
| Model | GX | Drive | 4WD |
| Trim | GX 550 | Maker | TOYOTA MOTOR CORPORATION |
| Body | Sport Utility Vehicle | Plant | Tahara, Aichi, Japan |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/gx/2024

**4** recalls listed by Transport Canada for this model year

### Visual system

2026261 27 May 2026

Issue: On certain vehicles, a software problem could cause the combination meter in the instrument cluster not to display when the vehicle is started. As a result, you may not be able to see certain information about the vehicle, including warning lights and malfunction tell-tales. Note: This recall only affects vehicles equipped with a 12.3-inch display. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to update the combination meter software.

### Engine

2026241 20 May 2026

Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, metal debris could cause the crankshaft bearings to fail. If this happens, the engine may run rough or may not start. This could also cause the engine to stall while driving. Note: This recall only affects certain vehicles equipped with a 3.4L twin-turbo engine. This recall replaces Transport Canada recall No. 2025-614. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to inspect the No. 1 main bearing for abnormal wear and, if necessary, replace the engine.

### Engine

2025614 6 Nov 2025

This recall was replaced by Transport Canada recall no. 2026-241. Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, metal debris could cause the crankshaft bearings to fail. If this happens, the engine may run rough or may not start. This could also cause the engine to stall while driving. Note: This recall only affects certain vehicles equipped with a 3.4L twin-turbo engine. This recall is an expansion of Transport Canada Recall No. 2024-304. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. The corrective actions for this recall are under development.

### Visual system

2025594 30 Oct 2025

Issue: Under certain conditions, a software problem could cause the rearview camera image to freeze or not to display. If this happens, the rearview image may not display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects certain vehicles equipped with a panoramic view monitor system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners in writing and advise you to take your vehicle to a dealership to update the parking assist ECU software.

Listed for the model year, not checked against your VIN. Lexus confirms which apply.
Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.
www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $117,898[5], $14,010 over the median of $103,888[4].

| | |
|---|---|
| Lowest ask | $93,739 |
| Middle half | $96,998 – $114,195 |
| Median ask | $103,888 |
| This car | $117,898 |

Same model year · 9 live listings · as of 27 Oct 2026

OTHER 2024 LEXUS GX LISTINGS [5]

| | |
|---|---|
| Calgary, AB · 32,000 km | $114,195 |
| Calgary, AB · 24,154 km | $114,898 |
| Nepean, ON · 64,196 km | $96,998 |
| Richmond Hill, ON · 48,206 km | $93,990 |
| Brampton, ON · 29,729 km | $93,739 |
| Nepean, ON · 22,365 km | $96,998 |

## §4 EVENTS

| | |
|---|---|
| 2024 | Model year 2024[1]<br>Assembly plant Tahara, Aichi, Japan |
| 30 Oct 2025 | Transport Canada recall 2025594[2]<br>Issued for the model year · Visual system |
| 6 Nov 2025 | Transport Canada recall 2025614[2]<br>Issued for the model year · Engine |
| 20 May 2026 | Transport Canada recall 2026241[2]<br>Issued for the model year · Engine |
| 27 May 2026 | Transport Canada recall 2026261[2]<br>Issued for the model year · Visual system |

26 Oct 2026 **Listed for sale, Calgary, AB**[5]
Lexus Of Royal Oak · asking $117,898

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 9 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.