Register entry, as of 28 October 2026 Listed for sale Record ID fcc8f807e2de

2018 Toyota RAV4 Ltd

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTM	DJREV	0	J	D	203990
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Corporation	RAV4 · 2.5 L	Computes	2018	Obu	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.5 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	RAV4	Drive	4WD
Trim	Ltd	Maker	TOYOTA MOTOR CORPORATION
Body	Sport Utility Vehicle	Plant	Obu, Aichi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/rav4/2018

5 recalls listed by Transport Canada for this model year

Electrical

2023589 1 Nov 2023

Issue: On certain vehicles, the battery hold-down assembly may not properly secure certain 12 V aftermarket batteries. As a result, the battery could shift positions and cause the positive battery post to contact the hold down bracket. If this happens, there could be a short circuit. Safety Risk: A short circuit could create the risk of a fire. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to replace the battery clamp sub-assembly, battery tray, and positive terminal cover.

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Tires

2021157 17 Mar 2021

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could lead to a sudden loss of air pressure and could cause a tire failure. Note: This recall only affects certain Continental tires, with specific date codes and mold numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Toyota will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect and replace the tires, if necessary.

Accessories

2019428 23 Aug 2019

Issue: On certain vehicles, the hook and loop material used to attach the carpet to its underpadding may not be flame resistant. As a result, when it is tested alone, the loop fasteners do not meet the requirements of Canadian regulations. Safety Risk: As the carpet is always assembled, and the loop fasteners are very small, this problem does not create a safety risk. Corrective Action: This is not a recall. The company has made production changes to ensure that all new vehicles meet the requirements of Canadian regulations.

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $34,995[5], $12,249 over the median of $22,746[4].

Lowest ask	$19,888
Middle half	$21,593 – $29,745
Median ask	$22,746
This car	$34,995

Same configuration · 10 live listings · as of 28 Oct 2026

OTHER 2018 TOYOTA RAV4 LISTINGS [5]

Toronto, ON · 176,281 km	$18,495
Montréal-Nord, QC · 46,717 km	$21,977
Markham, ON · 199,904 km	$17,888
Chatham, ON · 35,000 km	$24,143
Boisbriand, QC · 124,839 km	$17,494
Grande Prairie, AB · 196,128 km	$20,559

§4 EVENTS

2018	Model year 2018[1] Assembly plant Obu, Aichi, Japan
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
23 Aug 2019	Transport Canada recall 2019428[2] Issued for the model year · Accessories
17 Mar 2021	Transport Canada recall 2021157[2] Issued for the model year · Tires
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
1 Nov 2023	Transport Canada recall 2023589[2] Issued for the model year · Electrical
15 Oct 2026	Listed for sale, Kelowna, BC[5] Okanagan Credit Centre · asking $34,995
27 Oct 2026	Listing last updated[5] asking $34,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 10 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.