Register entry, as of 28 October 2026 Listed for sale Record ID df9e792889c7

2019 Toyota C-HR LE/XLE/Limited

2.0 L, 4 cylinders · 4x2 · Crossover Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTN	KHMBX	4	K	1	046863
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Corporation	C-HR · 2.0 L	Computes	2019	Kanegasaki	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.0 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	C-HR	Drive	4x2
Trim	LE/XLE/Limited	Maker	TOYOTA MOTOR CORPORATION
Body	Crossover Utility Vehicle	Plant	Kanegasaki, Iwate, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/c-hr/2019

3 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Seats and restraints

2019618 11 Dec 2019

Issue: On certain vehicles, the rear seat belts may be assembled incorrectly. As a result, the seat belts may not properly lock-up in certain types of crashes. Safety Risk: A seat belt that does not work properly could increase the risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the rear seat belt assemblies. They will be replaced as necessary.

Suspension

2018559 11 Oct 2018

On certain vehicles, one or more of the rear axle bearing bolts may not have been properly tightened during assembly. This could cause the bolt(s) to become loose and eventually detach, which could damage the rear brakes or could cause the rear wheel(s) to detach. This may result in a reduction in brake performance and a loss of vehicle stability, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the rear axle hub bearing bolts. If a bolt is found to be loose or detached, the dealer will replace the rear axle hub bearing assembly and rear axle carrier sub-assembly.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $20,695[5], $715 over the median of $19,980[4].



Lowest ask	$17,950
Middle half	$18,400 – $21,508
Median ask	$19,980
This car	$20,695

Same configuration · 9 live listings · as of 28 Oct 2026

OTHER 2019 TOYOTA C-HR LISTINGS [5]

Toronto, ON · 138,000 km	$17,950
Burlington, ON · 120,722 km	$20,248
London, ON · 46,483 km	$21,720
Newmarket, ON · 135,941 km	$17,990
Orleans, ON · 72,301 km	$22,490
Toronto, ON · 111,326 km	$18,698

§4 EVENTS

2019	Model year 2019[1] Assembly plant Kanegasaki, Iwate, Japan
11 Oct 2018	Transport Canada recall 2018559[2] Issued for the model year · Suspension
11 Dec 2019	Transport Canada recall 2019618[2] Issued for the model year · Seats and restraints
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
28 Oct 2026	Listed for sale, Saint-raymond, QC[5] St-Raymond Toyota · asking $20,695

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 9 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.