

Register entry, as of 29 October 2026

Listed for sale

Record ID 987d9f4d19c8

2015 Buick Encore Premium

1.4 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KL4 CJHSB 9 F B 156150

WMI 1-3

Buick · GENERAL MOTORS...

DESCRIPTOR 4-8

Encore · 1.4 L

CHECK 9

Computes

YEAR 10

2015

PLANT 11

Bupyeong

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	1.4 L, 4 cylinders
Make	Buick	Fuel	Gasoline
Model	Encore	Drive	AWD
Trim	Premium	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Bupyeong, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/encore/2015

3 recalls listed by Transport Canada for this model year

Airbag

2016439 9 Sep 2016

On certain vehicles, the sensing and diagnostic module (SDM), which controls airbag and pretensioner deployment, contains a software defect which may prevent the deployment of frontal airbags and pretensioners in certain circumstances. Failure of frontal airbags and seatbelt pretensioners to deploy in a crash (when warranted) could increase the risk of injury. Correction: Dealers will reflash the SDM with new software. In vehicles with any previous deployment events recorded in the SDM, the dealers will replace the existing SDM with a new SDM containing the latest software. Note: This recall affects 2014-2017 model year Sierra LD/Silverado LD models and 2015-2016 model year Sierra HD/Silverado HD model vehicles.

Label

2015117 18 Mar 2015

Certain vehicles fail to comply with the requirements of Canada Motor Vehicle Safety Standard 110 – Tire Selection and Rims. The Tire and Loading Information Label does not contain the rim size information for the front or rear wheels, contrary to the requirements of the standard. This could result in incorrect replacement rims being installed on the vehicle, which could increase the risk of injury and/or damage to property. Correction: Dealers will provide new corrected labels.

Steering

2015107 12 Mar 2015

On certain vehicles, the steering column assembly housing may come into contact with the power steering printed circuit board. This contact could eventually cause enough wear on the power steering printed circuit board to cause a sudden loss of power steering assist. If the power steering assist is lost, a malfunction indicator light is displayed on the instrument panel to inform the driver. Steering control can be maintained, as the vehicle will revert to a manual steering mode, but will require greater driver effort particularly at low vehicle speeds. The sudden change in steering effort may increase the risk of a crash causing injury and/or property damage. Correction: Dealers will inspect, and if necessary, replace the steering column assembly.



Listed for the model year, not checked against your VIN. Buick confirms which apply.
Check your VIN with Buick Canada or call a Buick dealer with your VIN.
www.buick.ca/en/ownercenter/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$6,575^[5], \$4,415 under the median of \$10,990^[4].



Lowest ask	\$5,950
Middle half	\$8,495 – \$11,995
Median ask	\$10,990
This car	\$6,575

Same model year · 17 live listings · as of 29 Oct 2026

OTHER 2015 BUICK ENCORE LISTINGS ^[5]

Orangeville, ON · 217,464 km	\$6,610
Lévis, QC · 134,500 km	\$10,987
Sundridge, ON · 217,464 km	\$6,610
Orangeville, ON · 217,464 km	\$6,610
Orangeville, ON · 217,464 km	\$6,610
Orangeville, ON · 217,464 km	\$6,610

§4 EVENTS

2015	Model year 2015 ^[1] Assembly plant Bupyeong, South Korea
12 Mar 2015	Transport Canada recall 2015107 ^[2] Issued for the model year · Steering
18 Mar 2015	Transport Canada recall 2015117 ^[2] Issued for the model year · Label
9 Sep 2016	Transport Canada recall 2016439 ^[2] Issued for the model year · Airbag
29 Jul 2026	Listed for sale, Brampton, ON ^[5] Frost Chevrolet Buick GMC Cadillac Ltd · asking \$6,575
29 Oct 2026	Listing last updated ^[5] asking \$6,575

§5 DOCUMENTS

Window sticker This VIN reads as model year 1985 or 2015, before our coverage for this manufacturer.



SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 17 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

