Register entry, as of 27 October 2026 Listed for sale Record ID e034f6009955

2024 Hyundai Kona SEL

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KM8	HBCAB	6	R	U	095678
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai Motor Co	Kona · 2.0 L	Computes	2024	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	2.0 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Kona	Drive	4WD
Trim	SEL	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/kona/2024

5 recalls listed by Transport Canada for this model year

Seats and restraints

2026337 13 Jul 2026

Issue: On certain vehicles, the bracket that secures the rear center seat belt buckle may not have been manufactured properly. As a result, the seat belt could detach in a crash. Safety Risk: A seat belt that detaches in a crash could increase the risk of injury. Corrective Actions: To reduce the safety risk, Hyundai advises that you shouldn't transport a passenger in the rear center seat until the recall repairs are completed. Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to replace the rear center seat belt buckle.

Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Engine

2024255 30 Apr 2024

Issue: On certain vehicles, the exhaust gas recirculation (EGR) valve may not have been manufactured properly. As a result, the EGR valve could short circuit and cause a loss of power to the wheels. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to replace the EGR valve.

Electrical

2023709 26 Dec 2023

Issue: On certain vehicles, in the event of a crash, the 12 V battery cable(s) could contact the engine control module bracket. If this happens, there could be a short circuit. Safety Risk: A short circuit could create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to install a protective cover on the 12 V battery and alternator positive wiring.

Seats and restraints

2023526 22 Sep 2023

Issue: On certain vehicles, the rear outboard seat belt retractors may not have been manufactured correctly. As a result, the seat belts may not extend and/or retract correctly. Safety Risk: A seat belt that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the left and right-rear seat belt retractors, and replace them if necessary. Hyundai recommends that if you hear a noise when extending the seat belt or are unable to extend it, you should not transport a passenger in that seat, and you should contact a dealer immediately to have the vehicle inspected.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
www.hyundaicanada.com/en/owners-section/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,032[5], $40 over the median of $25,992[4].

Lowest ask	$22,200
Middle half	$23,814 – $26,995
Median ask	$25,992
This car	$26,032

Same configuration · 66 live listings · as of 27 Oct 2026

OTHER 2024 HYUNDAI KONA LISTINGS [5]

Langford, BC · 29,286 km	$30,542
Vaudreuil-Dorion, QC · 76,656 km	$21,995
Waterloo, ON · 27,012 km	$26,995
Ottawa, ON · 30,678 km	$26,499
London, ON · 41,089 km	$28,995
London, ON · 21,828 km	$27,395

§4 EVENTS

2024	Model year 2024[1] Assembly plant Ulsan, South Korea
22 Sep 2023	Transport Canada recall 2023526[2] Issued for the model year · Seats and restraints
26 Dec 2023	Transport Canada recall 2023709[2] Issued for the model year · Electrical
30 Apr 2024	Transport Canada recall 2024255[2] Issued for the model year · Engine
23 Sep 2024	Transport Canada recall 2024552[2] Issued for the model year · Label

13 Jul 2026	Transport Canada recall 2026337[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Tecumseh, ON[5] Windsor Hyundai · asking $26,032

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 66 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.