Register entry, as of 28 October 2026 Listed for sale Record ID b483d013c457

# 2026 Hyundai Kona SEL Convenience

2.0 L · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KM8 | HCCAB | 2 | T | U | 401554 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Hyundai Motor Co | Kona · 2.0 L | Computes | 2026 | Ulsan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2026 | Engine | 2.0 L |
| Make | Hyundai | Fuel | Gasoline |
| Model | Kona | Drive | 4WD |
| Trim | SEL Convenience | Maker | HYUNDAI MOTOR CO |
| Body | Sport Utility Vehicle | Plant | Ulsan, South Gyeongsang Province, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/kona/2026

**3** recalls listed by Transport Canada for this model year

### Seats and restraints

2026337 13 Jul 2026

Issue: On certain vehicles, the bracket that secures the rear center seat belt buckle may not have been manufactured properly. As a result, the seat belt could detach in a crash. Safety Risk: A seat belt that detaches in a crash could increase the risk of injury. Corrective Actions: To reduce the safety risk, Hyundai advises that you shouldn't transport a passenger in the rear center seat until the recall repairs are completed. Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to replace the rear center seat belt buckle.

### Steering

2026050 5 Feb 2026

Issue: On certain vehicles, the front steering knuckle(s) may not have been manufactured properly. As a result, the knuckle(s) could crack and/or break and cause a loss of steering control. Safety Risk: A loss of steering control could create the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the steering knuckle(s).

### Visual system

2026033 27 Jan 2026

Issue: On certain vehicles, a software problem could cause the instrument panel cluster to reboot while driving. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, tire pressure monitoring system (TPMS), warning lights and malfunction tell-tales. Note : For the Santa Fe model, this recall only affects the hybrid model. For the Palisade model, both gas and hybrid models are affected. For the Tucson model, gas, hybrid and plug-in hybrid (PHEV) models are affected. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and send a wireless over-the-air software update to eligible vehicles to update the instrument panel cluster software. Alternatively, you may schedule an appointment to have the update performed at a Hyundai dealership.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $29,988[5], $6,111 under the median of $36,099[4].

| | |
|---|---|
| Lowest ask | $28,907 |
| Middle half | $34,367 – $36,349 |
| Median ask | $36,099 |
| This car | $29,988 |

Same configuration · 168 live listings · as of 28 Oct 2026

### OTHER 2026 HYUNDAI KONA LISTINGS [5]

| | |
|---|---|
| Calgary, AB · 14 km | $39,099 |
| Moose Jaw, SK · 31,217 km | $33,987 |
| Halifax, NS · 18,407 km | $35,689 |
| Halifax, NS · 12,908 km | $35,689 |
| Repentigny, QC · 193 km | $37,271 |
| Maple Ridge, BC · 29,154 km | $30,908 |

## §4 EVENTS

| | |
|---|---|
| 2026 | Model year 2026[1]<br>Assembly plant Ulsan, South Gyeongsang Province, South Korea |
| 27 Jan 2026 | Transport Canada recall 2026033[2]<br>Issued for the model year · Visual system |
| 5 Feb 2026 | Transport Canada recall 2026050[2]<br>Issued for the model year · Steering |
| 13 Jul 2026 | Transport Canada recall 2026337[2]<br>Issued for the model year · Seats and restraints |
| 27 Oct 2026 | Listed for sale, Kamloops, BC[5]<br>Bannister Hyundai Kamloops · asking $29,988 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $29,988 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 168 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.