Register entry, as of 29 October 2026 Listed for sale Record ID 0ac865237b4a

# 2023 Hyundai Tucson SEL

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KM8 | JBCAE | 0 | P | U | 251724 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Hyundai Motor Co | Tucson · 2.5 L | Computes | 2023 | Ulsan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 2.5 L, 4 cylinders |
| Make | Hyundai | Fuel | Gasoline |
| Model | Tucson | Drive | 4WD |
| Trim | SEL | Maker | HYUNDAI MOTOR CO |
| Body | Sport Utility Vehicle | Plant | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/tucson/2023

**3** recalls listed by Transport Canada for this model year

### Accessories

2025702 18 Dec 2025

Issue: This recall is for certain trailer wiring harnesses that were installed before delivery or sold as a dealer accessory. On certain vehicles, the trailer wiring harness may not have been manufactured properly. As a result, water could leak into the harness and cause it to fail. If this happens, the trailer lights and/or the vehicle's stop lights may not work. This could also cause the wiring harness to short circuit. Note: This recall only affects certain vehicles equipped with a Hyundai Genuine accessory trailer wiring harness part number N7H03-AP100. Safety Risk: Vehicle and/or trailer lights that don't work could make the vehicle and/or trailer less visible and cause others not to recognize that the vehicle is braking or intends to turn or change lanes. These issues could increase the risk of a crash. Additionally, a short circuit can create the risk of a fire. Corrective Actions: Hyundai will notify owners in writing. The corrective actions for this recall are under development.

### Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

### Powertrain

2023414 27 Jul 2023

Issue: On certain vehicles, the circuit board for the transmission electric oil pump may be damaged. As a result, the circuit board could short circuit and overheat, and various electrical systems may not work properly. Safety Risk: A short circuit could create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the transmission electric oil pump controller, and replace it as necessary. Hyundai recommends parking your vehicle outside and away from other vehicles or buildings until the recall repairs are completed.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $25,995[5], $1,000 over the median of $24,995[4].

| | |
|---|---|
| Lowest ask | $14,899 |
| Middle half | $23,895 – $26,694 |
| Median ask | $24,995 |
| This car | $25,995 |

Same configuration · 65 live listings · as of 29 Oct 2026

### OTHER 2023 HYUNDAI TUCSON LISTINGS [5]

| | |
|---|---|
| Vernon, BC · 69,655 km | $36,998 |
| St-Félicien, QC · 60,577 km | $25,888 |
| Repentigny (Québec), QC · 87,264 km | $23,795 |
| Saint John, NB · 52,985 km | $25,156 |
| Longueuil, QC · 131,833 km | $27,955 |
| Saskatoon, SK · 41,260 km | $30,901 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant Ulsan, South Korea |
| 27 Jul 2023 | Transport Canada recall 2023414[2]<br>Issued for the model year · Powertrain |
| 23 Sep 2024 | Transport Canada recall 2024552[2]<br>Issued for the model year · Label |
| 18 Dec 2025 | Transport Canada recall 2025702[2]<br>Issued for the model year · Accessories |
| 27 Oct 2026 | Listed for sale, Rivière-du-Loup, QC[5]<br>Hyundai Riviere-Du-Loup · asking $25,995 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $25,995 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 65 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.