Register entry, as of 26 October 2026 Listed for sale Record ID 61c83735ff9b

# 2026 Hyundai Tucson SEL Convenience

1.6 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KM8 | JCDD1 | 3 | T | U | 536651 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Hyundai Motor Co | Tucson · 1.6 L | Computes | 2026 | Ulsan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2026 | Engine | 1.6 L, 4 cylinders |
| Make | Hyundai | Fuel | Gasoline |
| Model | Tucson | Drive | 4WD |
| Trim | SEL Convenience | Maker | HYUNDAI MOTOR CO |
| Body | Sport Utility Vehicle | Plant | Ulsan, South Gyeongsang Province, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/tucson/2026

**4** recalls listed by Transport Canada for this model year

### Lights and instruments

2026308 24 Jun 2026

Issue: On certain vehicles, a software problem could cause the instrument panel cluster to reboot while driving. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, warning lights and malfunction tell-tales. Note: This recall only affects hybrid (HEV) and plug-in hybrid (PHEV) models equipped with a heads-up display. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and send a wireless over-the-air software update to eligible vehicles to update the instrument panel cluster software. Alternatively, you may schedule an appointment to have the update performed at a Hyundai dealership.

### Other

2026238 19 May 2026

Issue: On certain vehicles, a software problem with the front camera could cause the forward collision avoidance (FCA) system to apply the vehicle's brakes suddenly. Note: For the Tucson model, this recall affects gas, hybrid (HEV) and plug-in hybrid (PHEV) models. Safety Risk: A vehicle that brakes suddenly when there's no risk of a collision could increase the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to update the front camera software.

### Airbag

2026199 20 Apr 2026

Issue: On certain vehicles, the side-impact sensors may not have been manufactured properly. As a result, the driver-front and passenger-front airbags may not work properly in a crash. Note: This recall also affects hybrid (HEV) and plug-in hybrid (PHEV) models. Safety Risk: Airbags that don't work properly could increase the risk of injury in a crash. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the side-impact sensors.

### Visual system

2026033 27 Jan 2026

Issue: On certain vehicles, a software problem could cause the instrument panel cluster to reboot while driving. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, tire pressure monitoring system (TPMS), warning lights and malfunction tell-tales. Note : For the Santa Fe model, this recall only affects the hybrid model. For the Palisade model, both gas and hybrid models are affected. For the Tucson model, gas, hybrid and plug-in hybrid (PHEV) models are affected. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and send a wireless over-the-air software update to eligible vehicles to update the instrument panel cluster software. Alternatively, you may schedule an appointment to have the update performed at a Hyundai dealership.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
www.hyundaicanada.com/en/owners-section/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $50,195[5], $4 under the median of $50,199[4].

| | |
|---|---|
| Lowest ask | $37,950 |
| Middle half | $47,521 – $50,921 |
| Median ask | $50,199 |
| This car | $50,195 |

Same configuration · 1,697 live listings · as of 26 Oct 2026

OTHER 2026 HYUNDAI TUCSON LISTINGS [5]

| | |
|---|---|
| Lethbridge, AB · 25,997 km | $39,909 |
| Ottawa, ON · 34,000 km | $33,888 |
| Kingston, ON · 10 km | $41,849 |
| Kingston, ON · 10 km | $41,849 |
| Kingston, ON · 10 km | $41,849 |
| Kingston, ON · 10 km | $38,149 |

## §4 EVENTS

| | |
|---|---|
| 2026 | Model year 2026[1]<br>Assembly plant Ulsan, South Gyeongsang Province, South Korea |
| 27 Jan 2026 | Transport Canada recall 2026033[2]<br>Issued for the model year · Visual system |
| 20 Apr 2026 | Transport Canada recall 2026199[2]<br>Issued for the model year · Airbag |
| 19 May 2026 | Transport Canada recall 2026238[2]<br>Issued for the model year · Other |

| | |
|---|---|
| 24 Jun 2026 | Transport Canada recall 2026308[2]<br>Issued for the model year · Lights and instruments |
| 26 Oct 2026 | Listed for sale, Oakville, ON[5]<br>Hyundai Of Oakville · asking $50,195 |

## §5 DOCUMENTS

Window sticker — We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 1,697 live listings, as of 26 Oct 2026

[5] Live public dealer listings on Cardog, as of 26 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.