Register entry, as of 28 October 2026 Listed for sale Record ID 5b3b618995a8

# 2014 Hyundai Tucson GLS (Middle Level)

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KM8 | JUCAG | 5 | E | U | 789764 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Hyundai Motor Co | Tucson · 2.4 L | Computes | 2014 | Ulsan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2014 | Engine | 2.4 L, 4 cylinders |
| Make | Hyundai | Fuel | Gasoline |
| Model | Tucson | Drive | 4WD |
| Trim | GLS (Middle Level) | Maker | HYUNDAI MOTOR CO |
| Body | Sport Utility Vehicle | Plant | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/tucson/2014

**11** recalls listed by Transport Canada for this model year

### Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

### Brakes

2023125 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

### Brakes

2022616 27 Oct 2022

Issue: On certain vehicles, the control module for the antilock brake system (ABS) could short circuit. Note: This recall doesn't affect vehicles equipped with smart cruise control (SCC). This recall replaces Transport Canada recall 2022-046. Vehicles that were already repaired under Hyundai recall R0208 don't require this repair. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS multi-fuse. Hyundai advises that you may continue to drive your vehicle, however recommends that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

### Engine

2022244 8 May 2022

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. This is an expansion of R0180 (Transport Canada #2021-575). Any vehicle that received a software update under campaign R0180 does not require this update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

### Brakes

2022046 3 Feb 2022

This recall was replaced by Transport Canada Recall No. 2022-616 due to increase in the number of recalled vehicles. Issue: On certain vehicles, the control module for the antilock brake system (ABS) could short circuit. Note: This recall does not affect vehicles equipped with smart cruise control (SCC). Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS multi-fuse. Hyundai advises that you may continue to drive your vehicle, however recommends that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

### Engine

2021575 17 Sep 2021

This recall was replaced by Transport Canada Recall No. 2022-244. Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. All vehicles previously included in TC # 2021-034 are now part of this new campaign. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

5 more on the model-year record, cardog.app/tools/recalls/hyundai/tucson/2014

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $7,950[5], $2,049 under the median of $9,999[4].




| | |
|---|---|
| Lowest ask | $4,455 |
| Middle half | $9,695 – $11,488 |
| Median ask | $9,999 |
| This car | $7,950 |

Same configuration · 9 live listings · as of 28 Oct 2026

### OTHER 2014 HYUNDAI TUCSON LISTINGS [5]

| | |
|---|---|
| Longueuil, QC · 184,072 km | $9,695 |
| Kelowna, BC · 260,625 km | $4,455 |
| 100 Mile House, BC · 260,625 km | $4,455 |
| Chatham-Kent, ON · 106,133 km | $11,388 |

| | |
|---|---|
| Etobicoke, ON · 119,887 km | $11,488 |
| Saskatoon, SK · 15,000 km | $18,995 |

## §4 EVENTS

| | |
|---|---|
| 2014 | Model year 2014[1]<br>Assembly plant Ulsan, South Korea |
| 20 May 2014 | Transport Canada recall 2014177[2]<br>Issued for the model year · Airbag |
| 10 Jan 2019 | Transport Canada recall 2019012[2]<br>Issued for the model year · Engine |
| 11 Mar 2019 | Transport Canada recall 2019130[2]<br>Issued for the model year · Engine |
| 16 Dec 2019 | Transport Canada recall 2019640[2]<br>Issued for the model year · Engine |
| 27 Jan 2021 | Transport Canada recall 2021034[2]<br>Issued for the model year · Engine |
| 17 Sep 2021 | Transport Canada recall 2021575[2]<br>Issued for the model year · Engine |
| 3 Feb 2022 | Transport Canada recall 2022046[2]<br>Issued for the model year · Brakes |
| 8 May 2022 | Transport Canada recall 2022244[2]<br>Issued for the model year · Engine |
| 27 Oct 2022 | Transport Canada recall 2022616[2]<br>Issued for the model year · Brakes |
| 8 Mar 2023 | Transport Canada recall 2023125[2]<br>Issued for the model year · Brakes |
| 23 Sep 2024 | Transport Canada recall 2024552[2]<br>Issued for the model year · Label |
| 26 Oct 2026 | Listed for sale, Quebec, QC[5]<br>autojeanvezina.com · asking $7,950 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $7,950 |

## §5 DOCUMENTS

Window sticker — We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 9 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.