Register entry, as of 28 November 2026 Listed for sale Record ID cf9e606dc0b5

2015 Hyundai Tucson GLS (Middle)

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KM8	JUCAG	9	F	U	045490
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Hyundai Motor Co	Tucson · 2.4 L	Computes	2015	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.4 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Tucson	Drive	4WD
Trim	GLS (Middle)	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/tucson/2015

10 recalls listed by Transport Canada for this model year

Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Brakes

2023125 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

Brakes

2022616 27 Oct 2022

Issue: On certain vehicles, the control module for the antilock brake system (ABS) could short circuit. Note: This recall doesn't affect vehicles equipped with smart cruise control (SCC). This recall replaces Transport Canada recall 2022-046. Vehicles that were already repaired under Hyundai recall R0208 don't require this repair. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS multi-fuse. Hyundai advises that you may continue to drive your vehicle, however recommends that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

Engine

2022244 8 May 2022

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. This is an expansion of R0180 (Transport Canada #2021-575). Any vehicle that received a software update under campaign R0180 does not require this update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

Brakes

2022046 3 Feb 2022

This recall was replaced by Transport Canada Recall No. 2022-616 due to increase in the number of recalled vehicles. Issue: On certain vehicles, the control module for the antilock brake system (ABS) could short circuit. Note: This recall does not affect vehicles equipped with smart cruise control (SCC). Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS multi-fuse. Hyundai advises that you may continue to drive your vehicle, however recommends that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

Engine

2021575 17 Sep 2021

This recall was replaced by Transport Canada Recall No. 2022-244. Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. All vehicles previously included in TC # 2021-034 are now part of this new campaign. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

4 more on the model-year record, cardog.app/tools/recalls/hyundai/tucson/2015

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $12,990[5], $3,491 over the median of $9,499[4].



Lowest ask	$5,295
Middle half	$6,845 – $11,242
Median ask	$9,499
This car	$12,990

Same model year · 15 live listings · as of 28 Nov 2026

OTHER 2015 HYUNDAI TUCSON LISTINGS [5]

St-Basile-Le-Grand, QC · 185,332 km	$5,990
Saskatoon, SK · 155,701 km	$11,495
Whitby, ON · 139,132 km	$9,995
Sainte-Rose, QC · 200,984 km	$5,295

Surrey, BC · 110,148 km	$12,350
Toronto, ON · 217,959 km	$9,499

§4 EVENTS

2015	Model year 2015[1] Assembly plant Ulsan, South Korea
10 Jan 2019	Transport Canada recall 2019012[2] Issued for the model year · Engine
11 Mar 2019	Transport Canada recall 2019130[2] Issued for the model year · Engine
16 Dec 2019	Transport Canada recall 2019640[2] Issued for the model year · Engine
27 Jan 2021	Transport Canada recall 2021034[2] Issued for the model year · Engine
17 Sep 2021	Transport Canada recall 2021575[2] Issued for the model year · Engine
3 Feb 2022	Transport Canada recall 2022046[2] Issued for the model year · Brakes
8 May 2022	Transport Canada recall 2022244[2] Issued for the model year · Engine
27 Oct 2022	Transport Canada recall 2022616[2] Issued for the model year · Brakes
8 Mar 2023	Transport Canada recall 2023125[2] Issued for the model year · Brakes
23 Sep 2024	Transport Canada recall 2024552[2] Issued for the model year · Label
22 Nov 2026	Listed for sale, Winnipeg, MB[5] Crown Honda · asking $12,990
27 Nov 2026	Listing last updated[5] asking $12,990

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 15 live listings, as of 28 Nov 2026

[5] Live public dealer listings on Cardog, as of 28 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.