Register entry, as of 29 October 2026 Listed for sale Record ID 196f9e15dc71

# 2021 Hyundai Kona SE

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KM8 | K1CAA | 6 | M | U | 624359 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Hyundai Motor Co | Kona · 2.0 L | Computes | 2021 | Ulsan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 2.0 L, 4 cylinders |
| Make | Hyundai | Fuel | Gasoline |
| Model | Kona | Drive | 4WD |
| Trim | SE | Maker | HYUNDAI MOTOR CO |
| Body | Sport Utility Vehicle | Plant | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/kona/2021

**5** recalls listed by Transport Canada for this model year

### Other

2025636 17 Nov 2025

Issue : Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

### Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

### Electrical

2022728 16 Dec 2022

Issue: On certain electric vehicles, the electric power control unit (EPCU) may not be sealed correctly. As a result, coolant could leak inside the EPCU and onto the circuit board. If this happens, the vehicle could suddenly lose power to the wheels. Safety Risk: A sudden loss of power to the wheels may increase the risk of a crash. Corrective Action: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, replace the EPCU.

### Engine

2021252 28 Apr 2021

Issue: On certain vehicles, the engine's piston oil rings may be defective. This can cause engine wear that can lead to increased oil consumption. Eventually, this can create abnormal engine noise and the oil pressure warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This only affects vehicles equipped with a 2.0 L Nu MPI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the engine. The engine will be replaced, if necessary. Hyundai is also developing a Piston-ring Noise Sensing System (PNSS) software update to be installed when available; it will alert the driver of potential damage before an engine failure occurs.

### Brakes

2020593 2 Dec 2020

Issue: On certain vehicles, an abnormal sensor signal to the Integrated Electronic Brake (IEB) system could cause a sudden reduction in braking performance. If this happens, a brake warning light will turn on in the instrument cluster. Safety Risk: Reduced brake performance can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to update the IEB system software.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $18,795[5], $1,800 over the median of $16,995[4].

| | |
|---|---|
| Lowest ask | $9,995 |
| Middle half | $14,888 – $18,601 |
| Median ask | $16,995 |
| This car | $18,795 |

Same configuration · 21 live listings · as of 29 Oct 2026

#### OTHER 2021 HYUNDAI KONA LISTINGS [5]

| | |
|---|---|
| Repentigny, QC · 90,197 km | $17,989 |
| Repentigny, QC · 130,935 km | $14,990 |
| Yarmouth, NS · 102,342 km | $19,995 |
| Orangeville, ON · 95,396 km | $17,496 |
| Mississauga, ON · 113,819 km | $14,788 |
| Leamington, ON · 113,819 km | $14,788 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Ulsan, South Korea |
| 2 Dec 2020 | Transport Canada recall 2020593[2]<br>Issued for the model year · Brakes |

| | |
|---|---|
| 28 Apr 2021 | Transport Canada recall 2021252[2]<br>Issued for the model year · Engine |
| 16 Dec 2022 | Transport Canada recall 2022728[2]<br>Issued for the model year · Electrical |
| 23 Sep 2024 | Transport Canada recall 2024552[2]<br>Issued for the model year · Label |
| 17 Nov 2025 | Transport Canada recall 2025636[2]<br>Issued for the model year · Other |
| 26 Oct 2026 | Listed for sale, Sherbrooke, QC[5]<br>Les Inventaires MT Inc. · asking $18,795 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $18,795 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 21 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.