

Register entry, as of 28 October 2026

Listed for sale

Record ID f9c41026fbaa

2023 Hyundai Kona Limited

1.6 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KM8 K5CA3 X P U 952295

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Kona · 1.6 L

CHECK 9

Computes

YEAR 10

2023

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	1.6 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Kona	Drive	4WD
Trim	Limited	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/kona/2023

4 recalls listed by Transport Canada for this model year

Other 2025636 17 Nov 2025

Issue : Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

Label 2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Fuel system 2024403 11 Jul 2024

Issue: On certain vehicles, the high-pressure fuel pump could fail. If this happens, the engine may run rough and the check engine light may turn on. This could also cause a sudden loss of engine power while driving. Note: For the Elantra, Kona and Veloster models, this recall only affects the N performance versions. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to update the engine control module software. The high-pressure fuel pump will be replaced, if necessary.



Powertrain

2023414 27 Jul 2023


Issue: On certain vehicles, the circuit board for the transmission electric oil pump may be damaged. As a result, the circuit board could short circuit and overheat, and various electrical systems may not work properly. Safety Risk: A short circuit could create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the transmission electric oil pump controller, and replace it as necessary. Hyundai recommends parking your vehicle outside and away from other vehicles or buildings until the recall repairs are completed.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
www.hyundaicanada.com/en/owners-section/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$29,895^[5], \$4,215 over the median of \$25,680^[4].



Lowest ask	\$22,999
Middle half	\$24,993 – \$26,788
Median ask	\$25,680
This car	\$29,895

Same configuration · 18 live listings · as of 28 Oct 2026

OTHER 2023 HYUNDAI KONA LISTINGS [5]

Cornwall, ON · 35,219 km	\$25,549
Maple Ridge, BC · 55,943 km	\$25,904
Maple Ridge, BC · 45,606 km	\$23,404
Rimouski, QC · 68,444 km	\$24,991
Rimouski, QC · 66,800 km	\$19,991
Rimouski, QC · 66,800 km	\$19,991

§4 EVENTS

2023	Model year 2023 ^[1] Assembly plant Ulsan, South Korea
27 Jul 2023	Transport Canada recall 2023414 ^[2] Issued for the model year · Powertrain
11 Jul 2024	Transport Canada recall 2024403 ^[2] Issued for the model year · Fuel system
23 Sep 2024	Transport Canada recall 2024552 ^[2] Issued for the model year · Label
17 Nov 2025	Transport Canada recall 2025636 ^[2] Issued for the model year · Other



27 Oct 2026 Listed for sale, St-Eustache, QC^[5]
ALBI Kia St-Eustache · asking \$29,895

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 18 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

