

Register entry, as of 29 October 2026

Listed for sale

Record ID 4d03fe3ebcc6

# 2010 Hyundai Veracruz GLS

3.8 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**KM8 NUDCC 1 A U 121214**

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Veracruz · 3.8 L

CHECK 9

Computes

YEAR 10

2010

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                    |
|------------|-----------------------|--------|--------------------|
| Model year | 2010                  | Engine | 3.8 L, 6 cylinders |
| Make       | Hyundai               | Fuel   | Gasoline           |
| Model      | Veracruz              | Drive  | 4WD                |
| Trim       | GLS                   | Maker  | HYUNDAI MOTOR CO   |
| Body       | Sport Utility Vehicle | Plant  | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/hyundai/veracruz/2010](https://cardog.app/tools/recalls/hyundai/veracruz/2010)

## 7 recalls listed by Transport Canada for this model year

**Label** 2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

**Brakes** 2024080 8 Feb 2024

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Note: This recall replaces recall R0246 (Transport Canada recall number 2023-527). For the Sonata model, only the Sonata Hybrid model is affected by this recall. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

**Brakes** 2023527 22 Sep 2023

This recall was replaced by Transport Canada Recall No. 2024-080. Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.



## Engine

2020549 13 Nov 2020

Issue: On certain vehicles, engine oil can leak from the valve cover onto the alternator. If this happens, the charging system could stop working and cause a warning light to turn on. If you continue to drive the vehicle with this problem, the engine could shut off while driving, and you may not be able to restart it. Note: This recall replaces R0090 (Transport Canada recall 2014-297). Vehicles that were repaired under that recall also require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to have an oil protector installed. Note: If the battery charging indicator light is on, Hyundai recommends that you should arrange to have the vehicle inspected and repaired at a dealer immediately.

## Electrical

2020233 27 May 2020

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness kit that could fail. Over time, this could result in a short circuit that can cause overheating of the control module. Note: This recall only affects Hyundai Genuine Accessory trailer wiring harness kits that were manufactured by third parties and sold in Canada. These kits may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A short circuit could create a fire risk. This risk remains even when the vehicle is parked. Corrective Actions: Hyundai will notify owners by mail and instruct you to inspect your vehicle to see if it has an affected trailer wiring harness installed. If it does, Hyundai will advise you to take your vehicle to a dealer to install a redesigned trailer wiring harness. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

## Engine

2014297 16 Jul 2014

This recall was replaced by Transport Canada Recall No. 2020-549. On certain vehicles, engine oil can leak onto the alternator, which could affect charging system function and potentially cause the engine to stall and not restart. This would result in a loss of motive power as well as affect power braking and power steering system function, which would unexpectedly increase steering and brake pedal effort, potentially increasing stopping distances and the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the front valve cover gasket and repair/replace the alternator, as necessary.

1 more on the model-year record, [cardog.app/tools/recalls/hyundai/veracruz/2010](https://cardog.app/tools/recalls/hyundai/veracruz/2010)

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.


Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.

[www.hyundaicanada.com/en/owners-section/recalls](https://www.hyundaicanada.com/en/owners-section/recalls)

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

§3 VALUE <sup>[4]</sup>

This car asks \$5,995<sup>[5]</sup>, \$1,250 over the median of \$4,745<sup>[4]</sup>.



|             |                   |
|-------------|-------------------|
| Lowest ask  | \$3,495           |
| Middle half | \$4,120 – \$5,370 |
| Median ask  | \$4,745           |
| This car    | \$5,995           |

Same model year · 2 live listings · as of 29 Oct 2026

OTHER 2010 HYUNDAI VERACRUZ LISTINGS <sup>[5]</sup>

Montréal, QC · 227,000 km

\$3,495

## §4 EVENTS

2010

Model year 2010<sup>[1]</sup>

Assembly plant Ulsan, South Korea



|             |                                                                                           |
|-------------|-------------------------------------------------------------------------------------------|
| 25 Sep 2013 | Transport Canada recall 2013325 <sup>[2]</sup><br>Issued for the model year · Electrical  |
| 16 Jul 2014 | Transport Canada recall 2014297 <sup>[2]</sup><br>Issued for the model year · Engine      |
| 27 May 2020 | Transport Canada recall 2020233 <sup>[2]</sup><br>Issued for the model year · Electrical  |
| 13 Nov 2020 | Transport Canada recall 2020549 <sup>[2]</sup><br>Issued for the model year · Engine      |
| 22 Sep 2023 | Transport Canada recall 2023527 <sup>[2]</sup><br>Issued for the model year · Brakes      |
| 8 Feb 2024  | Transport Canada recall 2024080 <sup>[2]</sup><br>Issued for the model year · Brakes      |
| 23 Sep 2024 | Transport Canada recall 2024552 <sup>[2]</sup><br>Issued for the model year · Label       |
| 5 Oct 2026  | Listed for sale, Saskatoon, SK <sup>[5]</sup><br>Prairie West Automotive · asking \$5,995 |
| 29 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$5,995                                     |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                              |
|---------------------------------------------------------------------|------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 2 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 29 Oct 2026                 |
| [3] NHTSA recall records (United States), listed for the model year |                                                                              |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

