Register entry, as of 27 October 2026 Listed for sale Record ID b4bf22428813

# 2024 Hyundai Palisade XRT

3.8 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KM8 | R3DGE | 6 | R | U | 792471 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Hyundai Motor Co | Palisade · 3.8 L | Computes | 2024 | Ulsan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2024 | Engine | 3.8 L, 6 cylinders |
| Make | Hyundai | Fuel | Gasoline |
| Model | Palisade | Drive | 4WD |
| Trim | XRT | Maker | HYUNDAI MOTOR CO |
| Body | Sport Utility Vehicle | Plant | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/palisade/2024

**5** recalls listed by Transport Canada for this model year

### Airbag

2026023 22 Jan 2026

Issue: On certain vehicles, the side curtain airbags may not deploy properly for third-row occupants in a crash. Safety Risk: A side curtain airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Hyundai will notify owners in writing. The corrective actions for this recall are under development.

### Seats and restraints

2025476 11 Sep 2025

Issue: On certain vehicles, the driver, front passenger and second-row outboard seat belt buckle(s) may not have been manufactured properly. As a result, the seat belt(s) may not latch correctly and could detach in a crash. Safety Risk: A seat belt that detaches in a crash could increase the risk of injury. Corrective Actions: To reduce the safety risk, Hyundai recommends to firmly latch the seat belt and pull on it after latching to ensure it's secured until the recall repairs have been completed. Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the seat belt buckle(s).

### Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

### Engine

2024090 13 Feb 2024

Issue: On certain vehicles, the engine valve springs could break. As a result, the engine could fail and oil could leak onto hot components in the engine compartment. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Additionally, oil that leaks onto hot components can create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine.

### Powertrain

2023414 27 Jul 2023

Issue: On certain vehicles, the circuit board for the transmission electric oil pump may be damaged. As a result, the circuit board could short circuit and overheat, and various electrical systems may not work properly. Safety Risk: A short circuit could create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the transmission electric oil pump controller, and replace it as necessary. Hyundai recommends parking your vehicle outside and away from other vehicles or buildings until the recall repairs are completed.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $39,888[5], $2,376 under the median of $42,264[4].

| | |
|---|---|
| Lowest ask | $25,968 |
| Middle half | $40,796 – $44,914 |
| Median ask | $42,264 |
| This car | $39,888 |

Same configuration · 36 live listings · as of 27 Oct 2026

### OTHER 2024 HYUNDAI PALISADE LISTINGS [5]

| | |
|---|---|
| Peterborough, ON · 38,004 km | $43,988 |
| Laval, QC · 50,605 km | $41,742 |
| Petrolia, ON · 68,278 km | $41,999 |
| Kentville, NS · 47,128 km | $37,900 |
| Kentville, NS · 40,482 km | $41,788 |
| Embrun, ON · 36,468 km | $46,995 |

## §4 EVENTS

| | |
|---|---|
| 2024 | Model year 2024[1]<br>Assembly plant Ulsan, South Korea |
| 27 Jul 2023 | Transport Canada recall 2023414[2]<br>Issued for the model year · Powertrain |
| 13 Feb 2024 | Transport Canada recall 2024090[2]<br>Issued for the model year · Engine |

| | |
|---|---|
| 23 Sep 2024 | Transport Canada recall 2024552[2]<br>Issued for the model year · Label |
| 11 Sep 2025 | Transport Canada recall 2025476[2]<br>Issued for the model year · Seats and restraints |
| 22 Jan 2026 | Transport Canada recall 2026023[2]<br>Issued for the model year · Airbag |
| 11 Sep 2026 | Listed for sale, Middleton, NS[5]<br>Bruce Ford Sales Ltd · asking $39,888 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $39,888 |

## §5 DOCUMENTS

Window sticker — We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 36 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.