Register entry, as of 27 October 2026 Listed for sale Record ID bed1bfbb613a

2021 Hyundai Palisade SEL w/ Convenience Pkg

3.8 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KM8	R3DHE	6	M	U	286694
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai Motor Co	Palisade · 3.8 L	Computes	2021	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.8 L, 6 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Palisade	Drive	4WD
Trim	SEL w/ Convenience Pkg	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/palisade/2021

7 recalls listed by Transport Canada for this model year

Airbag

2026023 22 Jan 2026

Issue: On certain vehicles, the side curtain airbags may not deploy properly for third-row occupants in a crash. Safety Risk: A side curtain airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Hyundai will notify owners in writing. The corrective actions for this recall are under development.

Seats and restraints

2025476 11 Sep 2025

Issue: On certain vehicles, the driver, front passenger and second-row outboard seat belt buckle(s) may not have been manufactured properly. As a result, the seat belt(s) may not latch correctly and could detach in a crash. Safety Risk: A seat belt that detaches in a crash could increase the risk of injury. Corrective Actions: To reduce the safety risk, Hyundai recommends to firmly latch the seat belt and pull on it after latching to ensure it's secured until the recall repairs have been completed. Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the seat belt buckle(s).

Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Visual system

2023148 17 Mar 2023

Issue: On certain vehicles, the windshield wiper motor may stop working when snow and/or ice builds up on the windshield. Note: This recall replaces Transport Canada Recall No. 2022-465. Vehicles that were already repaired under Hyundai recall campaign R0222 don't require this repair. Safety Risk: Windshield wipers that don't work properly could affect a driver's visibility. This could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the driver's windshield wiper arm. Hyundai advises that if the wipers stop working, you should clear any buildup of snow or ice before restarting the wipers.

Accessories

2022472 19 Aug 2022

Issue: Certain vehicles may be equipped with a 4-pin accessory trailer wiring harness kit that could fail. Over time, this could result in a short circuit that can cause the control module to overheat. Note: This recall only affects Hyundai Genuine 4-pin tow hitch wiring harness kits with the part number S8F67AC500. These kits may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to bring your vehicle to a dealership to inspect the trailer wiring harness kit. The dealer will repair or replace the trailer wiring harness, as necessary. To reduce the safety risk, Hyundai advises that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed. Note: Hyundai advises you to bring your vehicle to a dealership for this inspection even if it doesn't have a trailer wiring harness, so that the recall campaign can be listed as completed for your vehicle.

Visual system

2022465 16 Aug 2022

Issue: On certain vehicles, the windshield wiper motor may stop working when snow and/or ice builds up on the windshield. Safety Risk: Windshield wipers that don't work properly could affect a driver's visibility. This could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the driver's windshield wiper arm.

1 more on the model-year record, cardog.app/tools/recalls/hyundai/palisade/2021

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $24,995[5], the median[4].

Lowest ask	$16,995
Middle half	$23,428 – $27,749
Median ask	$24,995
This car	$24,995

Same configuration · 27 live listings · as of 27 Oct 2026

OTHER 2021 HYUNDAI PALISADE LISTINGS [5]

Vaudreuil-Dorion, QC · 111,913 km	$27,981
Ottawa, ON · 81,083 km	$32,888
Chambly, QC · 129,514 km	$24,999
Chambly, QC · 159,525 km	$22,999
Kamloops, BC · 129,890 km	$28,178
Kamloops, BC · 129,890 km	$28,178

§4 EVENTS

2021	Model year 2021[1] Assembly plant Ulsan, South Korea
26 Oct 2021	Transport Canada recall 2021652[2] Issued for the model year · Brakes
16 Aug 2022	Transport Canada recall 2022465[2] Issued for the model year · Visual system
19 Aug 2022	Transport Canada recall 2022472[2] Issued for the model year · Accessories
17 Mar 2023	Transport Canada recall 2023148[2] Issued for the model year · Visual system
23 Sep 2024	Transport Canada recall 2024552[2] Issued for the model year · Label
11 Sep 2025	Transport Canada recall 2025476[2] Issued for the model year · Seats and restraints
22 Jan 2026	Transport Canada recall 2026023[2] Issued for the model year · Airbag
25 Oct 2026	Listed for sale, Toronto, ON[5] Frontier Fine Cars · asking $24,995
27 Oct 2026	Listing last updated[5] asking $24,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 27 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.