

Register entry, as of 29 October 2026

Listed for sale

Record ID 32bc1aac51b4

2026 Hyundai Palisade Calligraphy

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KM8 RMESA X T U 084321

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Palisade · 2.5 L

CHECK 9

Computes

YEAR 10

2026

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2026	Engine	2.5 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Palisade	Drive	4WD
Trim	Calligraphy	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Gyeongsang Province, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/palisade/2026

3 recalls listed by Transport Canada for this model year

Seats and restraints

2026131 19 Mar 2026

Issue: On certain vehicles, the wiring for the third-row left-hand (driver's side) seat belt buckle could become damaged when the buckle is pulled. As a result, the seat belt status indicator in the instrument panel may incorrectly show that a seat belt is buckled when it's not. Safety Risk: A seat belt status indicator that doesn't work correctly could create confusion. Not wearing a seat belt increases the risk of injury in a crash. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to install an extension to the wiring harness. The dealer will replace the seat belt buckle assembly, if necessary.

Seats and restraints

2026121 17 Mar 2026

Issue: On certain vehicles, the second and third-row seats may not detect an obstruction when the power folding functions are used, including when using the automatic power folding (stow) or the one-touch tilt-and-slide (walk-in) features. If this happens, the seat(s) may not stop moving even if there's an obstruction. Safety Risk: A seat that doesn't stop moving could increase the risk of injury. Corrective actions: To reduce the safety risk, Hyundai advises you to ensure the seats are empty before using any power folding function and not to use the one-touch tilt-and-slide (walk-in) feature when entering or exiting the third-row seats. Hyundai will notify owners in writing and send a wireless over-the-air software update to eligible vehicles to update the seat controller and audio, visual, navigation software. Alternatively, you may schedule an appointment to have the update performed at a Hyundai dealership.



Visual system

2026033 27 Jan 2026

Issue: On certain vehicles, a software problem could cause the instrument panel cluster to reboot while driving. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, tire pressure monitoring system (TPMS), warning lights and malfunction tell-tales. Note : For the Santa Fe model, this recall only affects the hybrid model. For the Palisade model, both gas and hybrid models are affected. For the Tucson model, gas, hybrid and plug-in hybrid (PHEV) models are affected. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and send a wireless over-the-air software update to eligible vehicles to update the instrument panel cluster software. Alternatively, you may schedule an appointment to have the update performed at a Hyundai dealership.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.

www.hyundaicanada.com/en/owners-section/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$68,199^[5], the median^[4].



Lowest ask	\$58,067
Middle half	\$65,938 – \$68,649
Median ask	\$68,199
This car	\$68,199

Same configuration · 51 live listings · as of 29 Oct 2026

OTHER 2026 HYUNDAI PALISADE LISTINGS [5]

Barrie, ON · 28,655 km	\$56,988
Orangeville, ON · 15,000 km	\$60,971
Victoria, BC · 312 km	\$63,049
Victoria, BC · 689 km	\$62,699
Victoria, BC · 21 km	\$62,699
Victoria, BC · 17 km	\$62,649

§4 EVENTS

2026	Model year 2026 ^[1] Assembly plant Ulsan, South Gyeongsang Province, South Korea
27 Jan 2026	Transport Canada recall 2026033 ^[2] Issued for the model year · Visual system
17 Mar 2026	Transport Canada recall 2026121 ^[2] Issued for the model year · Seats and restraints
19 Mar 2026	Transport Canada recall 2026131 ^[2] Issued for the model year · Seats and restraints



29 Oct 2026 Listed for sale, Dorval, QC^[5]
Hyundai West Island · asking \$68,199

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 51 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

