Register entry, as of 29 October 2026 Listed for sale Record ID 4b5661f58322

2018 Hyundai Santa Fe SE Premium pkg

3.3 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KM8	SNDHF	7	J	U	269130
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Hyundai Motor Co	Santa Fe · 3.3 L	Computes	2018	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.3 L, 6 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Santa Fe	Drive	4WD
Trim	SE Premium pkg	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/santa-fe/2018

5 recalls listed by Transport Canada for this model year

Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Brakes

2023125 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

Brakes

2022616 27 Oct 2022

Issue: On certain vehicles, the control module for the antilock brake system (ABS) could short circuit. Note: This recall doesn't affect vehicles equipped with smart cruise control (SCC). This recall replaces Transport Canada recall 2022-046. Vehicles that were already repaired under Hyundai recall R0208 don't require this repair. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS multi-fuse. Hyundai advises that you may continue to drive your vehicle, however recommends that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes

2022046 3 Feb 2022

This recall was replaced by Transport Canada Recall No. 2022-616 due to increase in the number of recalled vehicles. Issue: On certain vehicles, the control module for the antilock brake system (ABS) could short circuit. Note: This recall does not affect vehicles equipped with smart cruise control (SCC). Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS multi-fuse. Hyundai advises that you may continue to drive your vehicle, however recommends that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

Steering

2018105 23 Feb 2018

On certain vehicles, the steering wheel assembly may contain manufacturing defect, and could separate from the steering column while driving. This could result in a crash causing injury and/or damage to property. Correction: Dealers will inspect and if necessary install a revised steering wheel assembly.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $14,490[5], the median[4].

Lowest ask	$6,995
Middle half	$12,295 – $15,727
Median ask	$14,490
This car	$14,490

Same configuration · 13 live listings · as of 29 Oct 2026

OTHER 2018 HYUNDAI SANTA FE LISTINGS [5]

Williams Lake, BC · 121,230 km	$14,900
Ottawa, ON · 94,190 km	$15,995
Thunder Bay, ON · 94,190 km	$15,995
Thunder Bay, ON · 94,190 km	$15,995
Laval, QC · 81,928 km	$14,286
Thunder Bay, ON · 94,190 km	$16,464

§4 EVENTS

2018	Model year 2018[1] Assembly plant Ulsan, South Korea
23 Feb 2018	Transport Canada recall 2018105[2] Issued for the model year · Steering
3 Feb 2022	Transport Canada recall 2022046[2] Issued for the model year · Brakes

27 Oct 2022	Transport Canada recall 2022616[2] Issued for the model year · Brakes
8 Mar 2023	Transport Canada recall 2023125[2] Issued for the model year · Brakes
23 Sep 2024	Transport Canada recall 2024552[2] Issued for the model year · Label
26 Oct 2026	Listed for sale, Saint-Georges, QC[5] Sittelle Mazda · asking $14,490
27 Oct 2026	Listing last updated[5] asking $14,490

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 13 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.