

Register entry, as of 28 October 2026

Listed for sale

Record ID 5c6377a58dab

2017 Hyundai Ioniq HEV Limited w/Ultimate

1.6 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH C05LC 6 H U 020057

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Ioniq · 1.6 L

CHECK 9

Computes

YEAR 10

2017

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	1.6 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Ioniq	Drive	Not in the decode
Trim	HEV Limited w/Ultimate	Maker	HYUNDAI MOTOR CO
Body	Hatchback	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/ioniq/2017

4 recalls listed by Transport Canada for this model year

Powertrain

2021735 7 Dec 2021

Issue: On certain Ioniq EV models, the vehicle could accelerate after the accelerator pedal is released. Note: This problem can only happen under certain conditions after the vehicle enters "fail-safe" mode. Safety Risk: A vehicle that continues to accelerate could create the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you bring your vehicle to a dealer to update the electric power control unit (EPCU) software. The dealer will also add additional ground wiring between the drive motor/gear assembly and frame.

Electrical

2018562 12 Oct 2018

On certain Hybrid and Plug-In Hybrid (PHEV) vehicles, the main relay contacts in the Power Relay Assembly located underneath the rear seat may have an inadequate connection. This could increase electrical resistance and generate heat, increasing the risk of fire causing injury and/or damage to property. Correction: Dealers will inspect the Power Relay Assembly for signs of thermal damage. If no thermal damage is found, the main relay will be replaced. If signs of thermal damage exist, the Power Relay Assembly will be replaced. Note: This problem may cause the Illumination of the HEV warning light while driving and/or an inability to start the vehicle.

Electrical

2018203 25 Apr 2018

On certain vehicles, the hydraulic clutch actuator (HCA) was produced with burrs that could damage the inner oil seal. A damaged oil seal may create an oil leak that could result in an accumulation of oil in the phase cap area, and eventually cause an electrical short. This could increase the risk of an engine compartment fire causing injury and/or damage to property. Correction: Dealers will inspect and, if necessary, replace the hydraulic clutch actuator. Note: This recall only affects IONIQ HEV (Hybrid Electric Vehicle) and IONIQ PHEV (Plug-In Hybrid Electric Vehicle) models.



Electrical

2017433 7 Sep 2017


On certain electric vehicles, the aluminium housing of the Electronic Power Control Unit (EPCU) may contain voids which could allow coolant to contact the control unit's circuit board. This could result in a loss of motive power while the vehicle is in motion, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect, and if necessary, replace the EPCU assembly. Note: Ioniq Hybrid and plug-in Hybrid models are not affected by this recall.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
www.hyundaicanada.com/en/owners-section/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$17,995^[5], \$4,053 over the median of \$13,942^[4].



Lowest ask	\$8,750
Middle half	\$11,934 – \$15,665
Median ask	\$13,942
This car	\$17,995

Same model year · 4 live listings · as of 28 Oct 2026

OTHER 2017 HYUNDAI IONIQ LISTINGS ^[5]

Oshawa, ON · 129,039 km \$12,995

§4 EVENTS

2017	Model year 2017 ^[1] Assembly plant Ulsan, South Korea
7 Sep 2017	Transport Canada recall 2017433 ^[2] Issued for the model year · Electrical
25 Apr 2018	Transport Canada recall 2018203 ^[2] Issued for the model year · Electrical
12 Oct 2018	Transport Canada recall 2018562 ^[2] Issued for the model year · Electrical
7 Dec 2021	Transport Canada recall 2021735 ^[2] Issued for the model year · Powertrain
26 Oct 2026	Listed for sale, St-Jean-Sur-Richelieu, QC ^[5] Haut-Richelieu Volkswagen · asking \$17,995
28 Oct 2026	Listing last updated ^[5] asking \$17,995



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

