

Register entry, as of 29 October 2026

Listed for sale

Record ID 1366d9b77bff

# 2013 Hyundai Accent GLS, GS

1.6 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**KMH CT4AE X D U 307286**

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Accent · 1.6 L

CHECK 9

Computes

YEAR 10

2013

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |         |        |                    |
|------------|---------|--------|--------------------|
| Model year | 2013    | Engine | 1.6 L, 4 cylinders |
| Make       | Hyundai | Fuel   | Gasoline           |
| Model      | Accent  | Drive  | Not in the decode  |
| Trim       | GLS, GS | Maker  | HYUNDAI MOTOR CO   |
| Body       | Sedan   | Plant  | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/hyundai/accent/2013](https://cardog.app/tools/recalls/hyundai/accent/2013)

## 2 recalls listed by Transport Canada for this model year

### Brakes

2024080 8 Feb 2024

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Note: This recall replaces recall R0246 (Transport Canada recall number 2023-527). For the Sonata model, only the Sonata Hybrid model is affected by this recall. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

### Brakes

2023527 22 Sep 2023

This recall was replaced by Transport Canada Recall No. 2024-080. Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.  
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.  
[www.hyundaicanada.com/en/owners-section/recalls](https://www.hyundaicanada.com/en/owners-section/recalls)

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$3,495<sup>[5]</sup>, \$2,447 under the median of \$5,942<sup>[4]</sup>.



|             |                   |
|-------------|-------------------|
| Lowest ask  | \$1,845           |
| Middle half | \$4,234 – \$7,495 |
| Median ask  | \$5,942           |
| This car    | \$3,495           |

Same configuration · 8 live listings · as of 29 Oct 2026

## OTHER 2013 HYUNDAI ACCENT LISTINGS [5]

|                               |         |
|-------------------------------|---------|
| Longueuil, QC · 135,411 km    | \$6,955 |
| Charlesbourg, QC · 232,483 km | \$1,950 |
| Québec, QC · 237,489 km       | \$2,850 |
| Scarborough, ON · 61,282 km   | \$8,888 |
| Scarborough, ON · 104,277 km  | \$8,888 |
| Kingston, ON · 158,546 km     | \$7,495 |

## §4 EVENTS

|             |                                                                                       |
|-------------|---------------------------------------------------------------------------------------|
| 2013        | Model year 2013 <sup>[1]</sup><br>Assembly plant Ulsan, South Korea                   |
| 22 Sep 2023 | Transport Canada recall 2023527 <sup>[2]</sup><br>Issued for the model year · Brakes  |
| 8 Feb 2024  | Transport Canada recall 2024080 <sup>[2]</sup><br>Issued for the model year · Brakes  |
| 26 Oct 2026 | Listed for sale, Thetford-Mines, QC <sup>[5]</sup><br>Ruby Auto Inc. · asking \$3,495 |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$3,495                                 |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

|                                                                     |                                                                                 |
|---------------------------------------------------------------------|---------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 8 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 29 Oct 2026                    |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                 |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

