

Register entry, as of 29 October 2026

Listed for sale

Record ID 67b38d1f2130

2017 Hyundai Elantra GT Base, Value Edition, Tech Package

2.0 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH D35LH 2 H U 349748

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Elantra GT · 2.0 L

CHECK 9

Computes

YEAR 10

2017

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	2.0 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Elantra GT	Drive	Not in the decode
Trim	Base, Value Edition, Tech Package	Maker	HYUNDAI MOTOR CO
Body	Hatchback	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/elantra-gt/2017

3 recalls listed by Transport Canada for this model year

Brakes

2023125 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

Engine

2022244 8 May 2022

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. This is an expansion of R0180 (Transport Canada #2021-575). Any vehicle that received a software update under campaign R0180 does not require this update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.



Engine

2021575 17 Sep 2021

This recall was replaced by Transport Canada Recall No. 2022-244. Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. All vehicles previously included in TC # 2021-034 are now part of this new campaign. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.

Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.

www.hyundaicanada.com/en/owners-section/recalls

§3 VALUE [3]

This car asks \$12,597^[4], the median^[3].



Lowest ask	\$9,657
Middle half	\$11,127 – \$14,298
Median ask	\$12,597
This car	\$12,597

Same model year · 3 live listings · as of 29 Oct 2026

OTHER 2017 HYUNDAI ELANTRA GT LISTINGS [4]

St-Hubert, QC · 166,030 km	\$9,657
Calgary, AB · 60,263 km	\$15,999
Calgary, AB · 60,263 km	\$15,999
Calgary, AB · 60,263 km	\$15,999
Calgary, AB · 60,263 km	\$15,999
Calgary, AB · 60,263 km	\$15,999

§4 EVENTS

2017	Model year 2017 ^[1] Assembly plant Ulsan, South Korea
17 Sep 2021	Transport Canada recall 2021575 ^[2] Issued for the model year · Engine
8 May 2022	Transport Canada recall 2022244 ^[2] Issued for the model year · Engine
8 Mar 2023	Transport Canada recall 2023125 ^[2] Issued for the model year · Brakes



27 Oct 2026 Listed for sale, Sudbury, ON^[4]
Crosstown Cadillac · asking \$12,597

28 Oct 2026 Listing last updated^[4]
asking \$12,597

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- [1] Cardog identity register, decoded from the VIN
- [2] Transport Canada recall database, listed for the model year
- [3] Cardog market quote, same model year, 3 live listings, as of 29 Oct 2026
- [4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

