Register entry, as of 28 October 2026 Listed for sale Record ID b713cc5573e4

2020 Hyundai Elantra SEL, Value Edition & Limited

2.0 L, 4 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH	D84LF	9	L	U	946303
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai Motor Co	Elantra · 2.0 L	Computes	2020	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Elantra	Drive	FWD
Trim	SEL, Value Edition & Limited	Maker	HYUNDAI MOTOR CO
Body	Sedan	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/elantra/2020

2 recalls listed by Transport Canada for this model year

Engine

2021252 28 Apr 2021

Issue: On certain vehicles, the engine's piston oil rings may be defective. This can cause engine wear that can lead to increased oil consumption. Eventually, this can create abnormal engine noise and the oil pressure warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This only affects vehicles equipped with a 2.0 L Nu MPI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the engine. The engine will be replaced, if necessary. Hyundai is also developing a Piston-ring Noise Sensing System (PNSS) software update to be installed when available; it will alert the driver of potential damage before an engine failure occurs.

Wheels

2019498 7 Oct 2019

Issue: On certain cars, the wheel lug nuts were not properly tightened during assembly. This could cause the nuts to loosen or fall off, and could result in a wheel separating from the car. Note: For the Ioniq model, this recall only involves the Ioniq PHEV (Plug-In Hybrid Electric Vehicle) version. Safety Risk: A wheel separation could increase the risk of a crash. A wheel that detaches from a vehicle could create a hazard for other drivers and nearby people. Corrective Actions: The company will notify owners by mail and instruct them to take their car to a dealer to ensure the front and rear wheel nuts are properly tightened.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
www.hyundaicanada.com/en/owners-section/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $13,777[5], $1,218 under the median of $14,995[4].

Lowest ask	$8,499
Middle half	$13,002 – $16,995
Median ask	$14,995
This car	$13,777

Same configuration · 110 live listings · as of 28 Oct 2026

OTHER 2020 HYUNDAI ELANTRA LISTINGS [5]

Sherbrooke, QC · 11,677 km	$14,995
Saskatoon, SK · 108,723 km	$14,995
Mirabel, QC · 184,487 km	$9,995
Mcmasterville, QC · 128,121 km	$13,995
Beauport, QC · 38,982 km	$16,795
Embrun, ON · 141,056 km	$12,995

§4 EVENTS

2020	Model year 2020[1] Assembly plant Ulsan, South Korea
7 Oct 2019	Transport Canada recall 2019498[2] Issued for the model year · Wheels
28 Apr 2021	Transport Canada recall 2021252[2] Issued for the model year · Engine
26 Oct 2026	Listed for sale, Lévis, QC[5] normautos.com · asking $13,777
27 Oct 2026	Listing last updated[5] asking $13,777

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 110 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.