Register entry, as of 26 November 2026 Listed for sale Record ID 745a633e3c1a

# 2009 Hyundai Elantra HD

2.0 L · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KMH | DU45D | 1 | 9 | U | 713936 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Hyundai Motor Co | Elantra · 2.0 L | Computes | 2009 | Ulsan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2009 | Engine | 2.0 L |
| Make | Hyundai | Fuel | Gasoline |
| Model | Elantra | Drive | Not in the decode |
| Trim | HD | Maker | HYUNDAI MOTOR CO |
| Body | Sedan | Plant | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/elantra/2009

7 recalls listed by Transport Canada for this model year

### Airbag

2020159 14 Apr 2020

Issue: On certain vehicles, the driver-front airbag inflator could rupture when the airbag deploys in a crash. If this happens, the airbag may not fully inflate and fragments could be propelled toward vehicle occupants. UPDATE - October 14, 2024: This recall has been expanded to include certain Elantra Touring vehicles. Safety Risk: An airbag inflator that ruptures can create a risk of injury or death. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the driver-front airbag inflator.

### Brakes

2020045 7 Feb 2020

Issue: On certain vehicles equipped with an anti-lock brake system (ABS), moisture can enter the ABS control module and cause a short circuit. Safety Risk: A short circuit could create a fire risk. This can happen even if the vehicle is parked. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to install a relay to power off the ABS control module when the vehicle is turned off.

### Airbag

2018173 11 Apr 2018

Update - October 21, 2024: This parts recovery campaign was re-opened and its scope expanded. Hyundai Auto Canada is conducting a parts recovery campaign targeting 2009 Elantra and Elantra Touring vehicles built between January 15 and April 15, 2009. Owners of subject vehicles will be notified by mail and the driver frontal airbag module will be replaced at no charge. The parts are being recovered to aid in Hyundai's analysis in support of Transport Canada defect investigation file no. 3280-38-18. Note: No safety defect has been identified with these vehicles and this action is not being conducted under the requirements of the Motor Vehicle Safety Act.

### Airbag

2016151 8 Apr 2016

On certain vehicles, the frontal air bags and seatbelt pretensioners may inadvertently deploy while the vehicle is stopped or moving at slow speeds due to the improper calibration of the Airbag Control Unit (ACU). Unintended airbag / seatbelt pretensioner deployment, in a non-warranted (non-impact) situation, could startle the driver, and could result in a vehicle crash causing injury and/or property damage. Correction: Dealers will reprogram the Airbag Control Unit (ACU).

### Steering

2015089 27 Feb 2015

Certain vehicles equipped with electric power steering (EPS) may experience a sudden loss of power steering assist that could occur at any time while driving. If the electronic control unit (ECU) were to sense a discrepancy in the torque sensing circuitry of the steering system, and indicator lamp would illuminate in the instrument cluster to inform the driver that steering assist is no longer provided. Steering control could be maintained, as the vehicle will revert to a manual steering mode, but would require greater driver effort. The sudden change in steering may increase the risk of a crash causing injury and/or property damage. Correction: Dealers will update the electric power steering (EPS) control unit.

### Electrical

2013099 3 Apr 2013

On certain vehicles, the stop lamp switch may fail and cause intermittent operation of the brake lights. Failure of the brake lights to illuminate when the brake pedal is depressed could result in a crash causing property damage and/or personal injury. Correction: Dealers will replace the switch.

1 more on the model-year record, cardog.app/tools/recalls/hyundai/elantra/2009

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $2,200[5], $3,780 under the median of $5,980[4].




| | |
|---|---|
| Lowest ask | $2,200 |
| Middle half | $4,472 – $7,246 |
| Median ask | $5,980 |
| This car | $2,200 |

Same model year · 7 live listings · as of 26 Nov 2026

### OTHER 2009 HYUNDAI ELANTRA LISTINGS [5]

| | |
|---|---|
| London, ON · 78,215 km | $7,495 |
| London, ON · 73,932 km | $7,495 |
| London, ON · 225,398 km | $4,995 |
| Québec, QC · 138,870 km | $3,950 |
| Hamilton, ON · 144,363 km | $6,998 |
| Belleville, ON · 185,474 km | $5,980 |

## §4 EVENTS

2009 — Model year 2009[1]
Assembly plant Ulsan, South Korea

| | |
|---|---|
| 21 Aug 2008 | **Transport Canada recall 2008302**[2]<br>Issued for the model year · Fuel system |
| 3 Apr 2013 | **Transport Canada recall 2013099**[2]<br>Issued for the model year · Electrical |
| 27 Feb 2015 | **Transport Canada recall 2015089**[2]<br>Issued for the model year · Steering |
| 8 Apr 2016 | **Transport Canada recall 2016151**[2]<br>Issued for the model year · Airbag |
| 11 Apr 2018 | **Transport Canada recall 2018173**[2]<br>Issued for the model year · Airbag |
| 7 Feb 2020 | **Transport Canada recall 2020045**[2]<br>Issued for the model year · Brakes |
| 14 Apr 2020 | **Transport Canada recall 2020159**[2]<br>Issued for the model year · Airbag |
| 9 Nov 2026 | **Listed for sale, Woodstock, ON**[5]<br>Gord Anderson Automotive Group · asking $2,200 |
| 26 Nov 2026 | **Listing last updated**[5]<br>asking $2,200 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 7 live listings, as of 26 Nov 2026

[5] Live public dealer listings on Cardog, as of 26 Nov 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.