

Register entry, as of 27 October 2026

Listed for sale

Record ID 391be326999e

2018 Genesis G80 3.8 Base / 3.8 Premium / 3.8 Ultimate / 3.3T Sport/ 5.0 Ultimate

3.8 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH **GN4JE** **1** **J** **U** **228855**

WMI 1-3

Genesis · HYUNDAI MOTO...

DESCRIPTOR 4-8

G80 · 3.8 L

CHECK 9

Computes

YEAR 10

2018

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.8 L, 6 cylinders
Make	Genesis	Fuel	Gasoline
Model	G80	Drive	Not in the decode
Trim	3.8 Base / 3.8 Premium / 3.8 Ultimate / 3.3T Sport/ 5.0 Ultimate	Maker	HYUNDAI MOTOR CO
Body	Sedan	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/genesis/g80/2018

4 recalls listed by Transport Canada for this model year

Engine 2024158 8 Mar 2024

Issue: Under certain conditions, the left turbocharger oil feed pipe and hose assembly could become damaged. If this happens, oil could leak onto hot components. Note: This recall only affects vehicles equipped with a 3.3 L turbo (T-GDI) engine. This recall replaces recall R0159 (Transport Canada recall number 2019-350). Vehicles that were repaired under that recall also require this repair. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the left turbocharger oil feed pipe and hose assembly.

Electrical 2024089 13 Feb 2024

Issue: Under certain conditions, water could leak into the starter solenoid. If this happens, the solenoid could short circuit. Safety Risk: A short circuit can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to install an updated relay in the engine junction box. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes 2021133 10 Mar 2021

Issue: On certain vehicles, a problem in the control module for the antilock brake system (ABS) could cause it to short circuit. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.



Engine

2019350 17 Jul 2019

This recall was replaced by Transport Canada Recall No. 2024-158. Issue: On certain vehicles with a 3.3 litre turbocharged engine, the connections for the turbocharger oil feeder pipes may leak. This could result in oil leaking onto the exhaust manifold, increasing the risk of a fire. Safety Risk: A fire could create the risk of injury Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to replace the turbocharger oil feeder pipe.

Listed for the model year, not checked against your VIN. Genesis confirms which apply.
Check your VIN with Genesis Canada or call a Genesis dealer with your VIN.
acquisition.genesis.ca/en/recalls-lookup

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$19,488^[5], \$1,456 under the median of \$20,944^[4].



Lowest ask	\$19,488
Middle half	\$20,546 – \$22,241
Median ask	\$20,944
This car	\$19,488

Same model year · 4 live listings · as of 27 Oct 2026

OTHER 2018 GENESIS G80 LISTINGS ^[5]

Komoka, ON · 96,087 km	\$25,995
Vaughan, ON · 134,903 km	\$20,898
Halifax, NS · 135,487 km	\$20,990

§4 EVENTS

2018	Model year 2018 ^[1] Assembly plant Ulsan, South Korea
17 Jul 2019	Transport Canada recall 2019350 ^[2] Issued for the model year · Engine
10 Mar 2021	Transport Canada recall 2021133 ^[2] Issued for the model year · Brakes
13 Feb 2024	Transport Canada recall 2024089 ^[2] Issued for the model year · Electrical
8 Mar 2024	Transport Canada recall 2024158 ^[2] Issued for the model year · Engine
23 Sep 2026	Listed for sale, Etobicoke, ON ^[5] Bespoke Auto Gallery · asking \$19,488
26 Oct 2026	Listing last updated ^[5] asking \$19,488



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

