Register entry, as of 28 October 2026 Listed for sale Record ID 2703a862c010

2015 Hyundai Genesis 3.8L

3.8 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH	GN4JE	X	F	U	020450
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai Motor Co	Genesis · 3.8 L	Computes	2015	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.8 L, 6 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Genesis	Drive	Not in the decode
Trim	3.8L	Maker	HYUNDAI MOTOR CO
Body	Sedan	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/genesis/2015

6 recalls listed by Transport Canada for this model year

Electrical

2024089 13 Feb 2024

Issue: Under certain conditions, water could leak into the starter solenoid. If this happens, the solenoid could short circuit. Safety Risk: A short circuit can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to install an updated relay in the engine junction box. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes

2021133 10 Mar 2021

Issue: On certain vehicles, a problem in the control module for the antilock brake system (ABS) could cause it to short circuit. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes

2017300 8 Jun 2017

On certain vehicles equipped with a manual parking brake, the electrical switch which illuminates the parking brake warning light in the instrument cluster could become corroded. This could result in the parking brake warning light intermittently not illuminating when the parking brake is applied. A failure of the parking brake indicator to illuminate when the parking brake is applied can result in a driver misapplication of the parking brake, which may cause the following conditions: effect on vehicle acceleration, parking brake noise and/or parking brake “drag” and smoke and/or smell from driving with the applied parking brake. Correction: Dealers will replace the parking brake switch with a switch that revised contact material.

Electrical

2016390 10 Aug 2016

On certain vehicles equipped with the optional 7 inch LCD instrument cluster, there could be communication errors between the Audio, Visual, and Navigation (AVN) head unit and cluster. This could lead to the following symptoms: All warning lights illuminating, inaccurate speedometer/tachometer readings, no cluster illumination, turn signal indicators not illuminating when turn signals are activated and possibly a momentarily inoperative instrument cluster. Incorrect (or loss of) readings, messages, and warning lights displayed by the instrument cluster could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will reprogram the instrument cluster with updated software.

Tires

2015621 30 Dec 2015

On certain vehicles, the factory installed Hankook Ventus S1 Noble 2 tires could experience a rapid loss of air pressure due to a rupture of the sidewall under severe usage conditions. Rapid air loss could cause a loss of vehicle control, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the defective tires.

Electrical

2015090 27 Feb 2015

On certain vehicles, water could enter the rear combination lamp assemblies due to an improper seal. In some instances, accumulated water could affect the range switch signals. If this were to occur while the vehicle is stopped and the shifter were to be moved from Park to Reverse or Drive, or the shifter is moved from Drive to Reverse or Park, it could result in one or more of the following symptoms: the incorrect gear is displayed in the instrument panel, illumination of malfunction indicator lamp(s) and/or a delay in the engagement of the selected gear. An incorrect gear being selected could cause unintended vehicle movement, which could result in injury and/or damage to property. Correction: Dealers will apply pads to prevent water intrusion into the combination lamp housing.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $7,900[5], $3,510 under the median of $11,410[4].



Lowest ask	$7,900
Middle half	$8,970 – $14,248
Median ask	$11,410
This car	$7,900

Same model year · 8 live listings · as of 28 Oct 2026

OTHER 2015 HYUNDAI GENESIS LISTINGS [5]

Dartmouth, NS · 148,000 km	$14,995
Montréal, QC · 180,000 km	$8,895
Markham, ON · 107,200 km	$12,888
Calgary, AB · 143,332 km	$13,999
Toronto, ON · 199,594 km	$10,999
Toronto, ON · 150,821 km	$19,999

§4 EVENTS

2015	Model year 2015[1] Assembly plant Ulsan, South Korea
27 Feb 2015	Transport Canada recall 2015090[2] Issued for the model year · Electrical
30 Dec 2015	Transport Canada recall 2015621[2] Issued for the model year · Tires
10 Aug 2016	Transport Canada recall 2016390[2] Issued for the model year · Electrical
8 Jun 2017	Transport Canada recall 2017300[2] Issued for the model year · Brakes
10 Mar 2021	Transport Canada recall 2021133[2] Issued for the model year · Brakes
13 Feb 2024	Transport Canada recall 2024089[2] Issued for the model year · Electrical
3 Oct 2026	Listed for sale, Airdrie, AB[5] SJL Auto LTD · asking $7,900
28 Oct 2026	Listing last updated[5] asking $7,900

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 8 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.