

Register entry, as of 28 October 2026

Listed for sale

Record ID 33370d5e9353

2018 Hyundai Elantra GT Elantra GT

2.0 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH H35LE 9 J U 014483

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Elantra GT · 2.0 L

CHECK 9

Computes

YEAR 10

2018

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.0 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Elantra GT	Drive	Not in the decode
Trim	Elantra GT	Maker	HYUNDAI MOTOR CO
Body	Hatchback	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/elantra-gt/2018

3 recalls listed by Transport Canada for this model year

Engine

2022244 8 May 2022

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. This is an expansion of R0180 (Transport Canada #2021-575). Any vehicle that received a software update under campaign R0180 does not require this update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

Engine

2021575 17 Sep 2021

This recall was replaced by Transport Canada Recall No. 2022-244. Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. All vehicles previously included in TC # 2021-034 are now part of this new campaign. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.



Structure

2018730 21 Dec 2018

On certain Elantra GT models, the sunroof motor may have been programmed incorrectly and may be unable to detect an obstruction while closing the sunroof. This may cause the sunroof not to retract when a person or an object is in its path, which could increase the risk of injury. Correction: Dealers will inspect the sunroof motor and replace it if necessary.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
www.hyundaicanada.com/en/owners-section/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$12,495^[5], \$500 under the median of \$12,995^[4].



Lowest ask	\$8,999
Middle half	\$11,494 – \$13,249
Median ask	\$12,995
This car	\$12,495

Same configuration · 23 live listings · as of 28 Oct 2026

OTHER 2018 HYUNDAI ELANTRA GT LISTINGS [5]

Lévis, QC · 107,200 km	\$10,994
Port Coquitlam, BC · 135,000 km	\$11,100
Laval, QC · 153,000 km	\$8,999
Laval, QC · 109,000 km	\$9,495
Château-Richer, QC · 87,000 km	\$13,995
St-Hubert, QC · 196,172 km	\$9,657

§4 EVENTS

2018	Model year 2018 ^[1] Assembly plant Ulsan, South Korea
21 Dec 2018	Transport Canada recall 2018730 ^[2] Issued for the model year · Structure
17 Sep 2021	Transport Canada recall 2021575 ^[2] Issued for the model year · Engine
8 May 2022	Transport Canada recall 2022244 ^[2] Issued for the model year · Engine
29 Jul 2026	Listed for sale, Rivière-du-Loup, QC ^[5] Hyundai Riviere-Du-Loup · asking \$12,495
28 Oct 2026	Listing last updated ^[5] asking \$12,495



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 23 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

