

Register entry, as of 28 October 2026

Listed for sale

Record ID bf69d23a85ab

# 2019 Hyundai Elantra GT Elantra GT N Line

1.6 L, 4 cylinders · Hatchback · Gasoline

## VEHICLE IDENTIFICATION NUMBER [1]

**KMH H55LC X K U 103876**

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Elantra GT · 1.6 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                   |        |                    |
|------------|-------------------|--------|--------------------|
| Model year | 2019              | Engine | 1.6 L, 4 cylinders |
| Make       | Hyundai           | Fuel   | Gasoline           |
| Model      | Elantra GT        | Drive  | Not in the decode  |
| Trim       | Elantra GT N Line | Maker  | HYUNDAI MOTOR CO   |
| Body       | Hatchback         | Plant  | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/hyundai/elantra-gt/2019](https://cardog.app/tools/recalls/hyundai/elantra-gt/2019)

## 2 recalls listed by Transport Canada for this model year

## Engine

2022244 8 May 2022

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. This is an expansion of R0180 (Transport Canada #2021-575). Any vehicle that received a software update under campaign R0180 does not require this update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

## Engine

2021575 17 Sep 2021

This recall was replaced by Transport Canada Recall No. 2022-244. Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. All vehicles previously included in TC # 2021-034 are now part of this new campaign. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.



Listed for the model year, not checked against your VIN. Hyundai confirms which apply.  
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.  
[www.hyundaicanada.com/en/owners-section/recalls](http://www.hyundaicanada.com/en/owners-section/recalls)

### §3 VALUE [3]

This car asks \$16,590<sup>[4]</sup>, \$1,598 over the median of \$14,992<sup>[3]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$10,995            |
| Middle half | \$13,593 – \$15,880 |
| Median ask  | \$14,992            |
| This car    | \$16,590            |

Same model year · 18 live listings · as of 28 Oct 2026

#### OTHER 2019 HYUNDAI ELANTRA GT LISTINGS [4]

|                                |          |
|--------------------------------|----------|
| Mcmasterville, QC · 146,161 km | \$10,995 |
| Kamloops, BC · 110,419 km      | \$13,988 |
| Aylmer, ON · 183,000 km        | \$12,495 |
| Calgary, AB · 61,480 km        | \$17,888 |
| Sept-Îles, QC · 50,282 km      | \$15,819 |
| Vernon, BC · 161,664 km        | \$12,478 |

### §4 EVENTS

|             |                                                                                                      |
|-------------|------------------------------------------------------------------------------------------------------|
| 2019        | Model year 2019 <sup>[1]</sup><br>Assembly plant Ulsan, South Korea                                  |
| 17 Sep 2021 | Transport Canada recall 2021575 <sup>[2]</sup><br>Issued for the model year · Engine                 |
| 8 May 2022  | Transport Canada recall 2022244 <sup>[2]</sup><br>Issued for the model year · Engine                 |
| 28 Oct 2026 | Listed for sale, Saint-Jean-Sur-Richelieu, QC <sup>[4]</sup><br>Saint-Jean Hyundai · asking \$16,590 |

### §5 DOCUMENTS

Window sticker      We have not collected this label yet.

### SOURCES

- [1] Cardog identity register, decoded from the VIN  
[2] Transport Canada recall database, listed for the model year

- [3] Cardog market quote, same model year, 18 live listings, as of 28 Oct 2026  
[4] Live public dealer listings on Cardog, as of 28 Oct 2026



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

