

Register entry, as of 29 October 2026

Listed for sale

Record ID f5f343dc6232

2013 Hyundai Genesis Coupe GL

2.0 L, 4 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH HT6KD 4 D U 095900

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Genesis Coupe · 2.0 L

CHECK 9

Computes

YEAR 10

2013

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	2.0 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Genesis Coupe	Drive	Not in the decode
Trim	GL	Maker	HYUNDAI MOTOR CO
Body	Coupe	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/genesis-coupe/2013

6 recalls listed by Transport Canada for this model year

Powertrain

2024431 25 Jul 2024

Issue: On certain vehicles, the clutch ignition lock switch could fail. As a result, you may be able to start the vehicle when the clutch pedal is not depressed. This could cause the vehicle to move suddenly. Note: This recall only affects vehicles equipped with a manual transmission. Safety Risk: A parked vehicle that moves suddenly could create the risk of an injury or a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the clutch ignition lock switch.

Brakes

2024080 8 Feb 2024

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Note: This recall replaces recall R0246 (Transport Canada recall number 2023-527). For the Sonata model, only the Sonata Hybrid model is affected by this recall. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes

2023527 22 Sep 2023

This recall was replaced by Transport Canada Recall No. 2024-080. Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.



Brakes

2023125 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

Airbag

2016508 17 Oct 2016

On certain vehicles, objects or debris located under the front passenger seat could contact the electrical connector of the Occupant Classification System (OCS) and disconnect the connector if the seat is moved. This would disable the OCS and illuminate the instrument cluster Air Bag warning lamp. If the OCS is disabled, the first stage front passenger airbag would deploy in a frontal collision, regardless of the weight and size of the front passenger seat occupant. If the seat were to be occupied by a child seat or small statured occupant, it could increase the risk of injury. Additionally, this condition could cause the second stage of the frontal passenger airbag to fail to deploy during a crash, which could increase the risk of injury to the front passenger seat occupant. Correction: Dealers will secure the OCS connector to prevent it from being disconnected.

Powertrain

2015556 23 Nov 2015

On certain vehicles equipped with manual transmissions, the mounting bolts securing the rear differential may not have been properly fastened due to the suspension's rear crossmember and differential. Over time, the bolt(s) may loosen, and could cause the driveshaft to separate from the differential, which would result in excessive noise and loss of motive power, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect, and affect repairs as necessary.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.

Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.

www.hyundaicanada.com/en/owners-section/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$14,977^[5], \$1,979 over the median of \$12,998^[4].



Lowest ask	\$12,995
Middle half	\$12,997 – \$13,494
Median ask	\$12,998
This car	\$14,977

Same model year · 4 live listings · as of 29 Oct 2026

OTHER 2013 HYUNDAI GENESIS COUPE LISTINGS ^[5]

Sooke, BC · 156,000 km	\$12,998
Strathmore, AB · 127,783 km	\$12,999
Mississauga, ON · 133,535 km	\$8,995

§4 EVENTS

2013 Model year 2013^[1]
Assembly plant Ulsan, South Korea



23 Nov 2015	Transport Canada recall 2015556 ^[2] Issued for the model year · Powertrain
17 Oct 2016	Transport Canada recall 2016508 ^[2] Issued for the model year · Airbag
8 Mar 2023	Transport Canada recall 2023125 ^[2] Issued for the model year · Brakes
22 Sep 2023	Transport Canada recall 2023527 ^[2] Issued for the model year · Brakes
8 Feb 2024	Transport Canada recall 2024080 ^[2] Issued for the model year · Brakes
25 Jul 2024	Transport Canada recall 2024431 ^[2] Issued for the model year · Powertrain
18 Sep 2026	Listed for sale, Kelowna, BC ^[5] Russo Auto Sales · asking \$14,977
29 Oct 2026	Listing last updated ^[5] asking \$14,977

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

