Register entry, as of 29 October 2026 Listed for sale Record ID baa146631c77

2014 Hyundai Genesis Coupe GL

2.0 L, 4 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH	HT6KD	9	E	U	115253
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Hyundai Motor Co	Genesis Coupe · 2.0 L	Computes	2014	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	2.0 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Genesis Coupe	Drive	Not in the decode
Trim	GL	Maker	HYUNDAI MOTOR CO
Body	Coupe	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/genesis-coupe/2014

5 recalls listed by Transport Canada for this model year

Brakes — 2024080 — 8 Feb 2024

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Note: This recall replaces recall R0246 (Transport Canada recall number 2023-527). For the Sonata model, only the Sonata Hybrid model is affected by this recall. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes — 2023527 — 22 Sep 2023

This recall was replaced by Transport Canada Recall No. 2024-080. Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes — 2023125 — 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

Airbag

2016508 17 Oct 2016

On certain vehicles, objects or debris located under the front passenger seat could contact the electrical connector of the Occupant Classification System (OCS) and disconnect the connector if the seat is moved. This would disable the OCS and illuminate the instrument cluster Air Bag warning lamp. If the OCS is disabled, the first stage front passenger airbag would deploy in a frontal collision, regardless of the weight and size of the front passenger seat occupant. If the seat were to be occupied by a child seat or small statured occupant, it could increase the risk of injury. Additionally, this condition could cause the second stage of the frontal passenger airbag to fail to deploy during a crash, which could increase the risk of injury to the front passenger seat occupant. Correction: Dealers will secure the OCS connector to prevent it from being disconnected.

Powertrain

2015556 23 Nov 2015

On certain vehicles equipped with manual transmissions, the mounting bolts securing the rear differential may not have been properly fastened due to the suspension's rear crossmember and differential. Over time, the bolt(s) may loosen, and could cause the driveshaft to separate from the differential, which would result in excessive noise and loss of motive power, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect, and affect repairs as necessary.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $10,987[5], $1,006 under the median of $11,993[4].



Lowest ask	$7,950
Middle half	$10,228 – $13,249
Median ask	$11,993
This car	$10,987

Same model year · 4 live listings · as of 29 Oct 2026

OTHER 2014 HYUNDAI GENESIS COUPE LISTINGS [5]

Toronto, ON · 184,000 km	$7,950
North Vancouver District, BC · 142,177 km	$13,999

§4 EVENTS

2014	Model year 2014[1] Assembly plant Ulsan, South Korea
23 Nov 2015	Transport Canada recall 2015556[2] Issued for the model year · Powertrain
17 Oct 2016	Transport Canada recall 2016508[2] Issued for the model year · Airbag
8 Mar 2023	Transport Canada recall 2023125[2] Issued for the model year · Brakes

22 Sep 2023	Transport Canada recall 2023527[2] Issued for the model year · Brakes
8 Feb 2024	Transport Canada recall 2024080[2] Issued for the model year · Brakes
28 Oct 2026	Listed for sale, Blainville, QC[5] Hyundai Blainville · asking $10,987

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 4 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.