Register entry, as of 6 November 2026 Listed for sale Record ID d189d9236d6a

2021 Hyundai Sonata SEL

2.0 L, 4 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH	L34JJ	0	M	A	027925
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai Motor Co	Sonata · 2.0 L	Computes	2021	Asan	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Sonata	Drive	FWD
Trim	SEL	Maker	HYUNDAI MOTOR CO
Body	Sedan	Plant	Asan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/sonata/2021

4 recalls listed by Transport Canada for this model year

Fuel system — 2025637 — 18 Nov 2025

Issue: On certain vehicles, the check valve for the purge control system could wear and cause the fuel tank to expand. As a result, the fuel tank could contact hot components and fuel could leak. Note: This recall only affects certain vehicles equipped with a 1.6 L turbocharged engine. This safety recall replaces emissions recall no. ECR-H0003-24-005 (Hyundai recall no. C0566). Vehicles that were repaired under that recall also require this repair. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the check valve and update the electronic control unit (ECU) software. The dealer will also inspect the fuel tank and surrounding components and repair them, as necessary.

Powertrain — 2022568 — 6 Oct 2022

Issue: On certain vehicles, a fault in the transmission oil pump can cause the vehicle to enter "fail-safe mode". When this happens, a programming error can cause a sudden loss of power to the wheels after 20-30 seconds. Note: This recall only affects certain vehicles equipped with an 8-speed dual-clutch transmission (DCT). Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, replace the transmission. The dealer will also update the transmission control unit software.

Structure — 2021791 — 27 Dec 2021

Issue: On certain vehicles, the windshield may not be properly attached. As a result, the glass can become loose and could separate from the vehicle in a crash. Safety Risk: A windshield that detaches in a crash could create an increased risk of injury. Corrective Action: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to remove and reinstall the windshield.

Fuel system 2021426 9 Jul 2021

Issue: On certain vehicles, the connection between the high-pressure fuel pipe and fuel pump may not be properly sealed. As a result, a fuel leak could occur. Safety Risk: A fuel leak can create the risk of a fire. Corrective Action: Hyundai will notify owners by mail and instruct you to bring your vehicle to a dealer to inspect and replace the high-pressure fuel pipe, as required.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
www.hyundaicanada.com/en/owners-section/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,888[5], $936 over the median of $18,952[4].



Lowest ask	$9,900
Middle half	$16,990 – $21,236
Median ask	$18,952
This car	$19,888

Same model year · 40 live listings · as of 5 Nov 2026

OTHER 2021 HYUNDAI SONATA LISTINGS [5]

Port Hawkesbury, NS · 108,508 km	$17,942
Winnipeg, MB · 53,000 km	$27,498
Longueuil, QC · 140,981 km	$19,955
Ottawa, ON · 134,716 km	$17,588
Ottawa, ON · 134,716 km	$17,588
Calgary, AB · 120,119 km	$11,698

§4 EVENTS

2021	Model year 2021[1] Assembly plant Asan, South Korea
9 Jul 2021	Transport Canada recall 2021426[2] Issued for the model year · Fuel system
27 Dec 2021	Transport Canada recall 2021791[2] Issued for the model year · Structure
6 Oct 2022	Transport Canada recall 2022568[2] Issued for the model year · Powertrain
18 Nov 2025	Transport Canada recall 2025637[2] Issued for the model year · Fuel system
25 Oct 2026	Listed for sale, Gatineau, QC[5] Hull Hyundai · asking $19,888

4 Nov 2026	Listing last updated[5] asking $19,888

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 40 live listings, as of 5 Nov 2026

[5] Live public dealer listings on Cardog, as of 6 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.