Register entry, as of 28 October 2026 Listed for sale Record ID b26aab0d79e1

# 2021 Hyundai Elantra Blue

2.0 L, 4 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KMH | LM4AG | 1 | M | U | 086983 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Hyundai Motor Co | Elantra · 2.0 L | Computes | 2021 | Ulsan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 2.0 L, 4 cylinders |
| Make | Hyundai | Fuel | Gasoline |
| Model | Elantra | Drive | FWD |
| Trim | Blue | Maker | HYUNDAI MOTOR CO |
| Body | Sedan | Plant | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/elantra/2021

**4** recalls listed by Transport Canada for this model year

### Other

2025636 17 Nov 2025

Issue : Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

### Visual system

2024709 20 Nov 2024

Issue: On certain vehicles, the rearview camera may not have been manufactured properly. Over time, the camera could fail and cause the rearview camera image not to display. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: For the Santa Fe model, this recall affects both Santa Fe and Santa Fe Hybrid models. For the Elantra model, this recall affects both Elantra and Elantra Hybrid models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to replace the rearview camera.

### Powertrain

2023468 18 Aug 2023

Issue: On certain Elantra hybrid models, the vehicle could slowly accelerate after the brake pedal is released. Note: This problem can only happen under certain conditions after the vehicle enters "fail-safe" mode. Safety Risk: A vehicle that accelerates on its own could create the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to update the motor control unit (MCU) software.

### Seats and restraints

2022259 19 May 2022

Issue: On certain vehicles, there may be a problem with the driver and front passenger seat belt pretensioners. As a result, the seat belt pretensioners could explode in a crash. If this happens, small pieces of metal could hit people in the vehicle. Note: This recall affects Elantra and Elantra Hybrid models, and replaces recalls R0209 (Transport Canada No. 2022-098) and R0200 (Transport Canada No. 2021-627). Vehicles that were repaired under those recalls also require this repair. Safety Risk: A seat belt pretensioner that explodes could create a risk of injury. Corrective Actions: Hyundai will notify owners by mail and instruct you to bring your vehicle to a dealership to install a protective cap over the driver and front passenger's seat belt pretensioners.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
www.hyundaicanada.com/en/owners-section/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $17,495[5], $383 under the median of $17,878[4].

| | |
|---|---|
| Lowest ask | $9,999 |
| Middle half | $15,790 – $18,500 |
| Median ask | $17,878 |
| This car | $17,495 |

Same configuration · 85 live listings · as of 28 Oct 2026

OTHER 2021 HYUNDAI ELANTRA LISTINGS [5]

| | |
|---|---|
| Calgary, AB · 85,450 km | $17,995 |
| Victoriaville, QC · 65,708 km | $19,495 |
| Kamloops, BC · 90,942 km | $19,798 |
| Pembroke, ON · 75,577 km | $17,999 |
| Pembroke, ON · 115,956 km | $17,499 |
| Victoria, BC · 109,961 km | $18,327 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Ulsan, South Korea |
| 19 May 2022 | Transport Canada recall 2022259[2]<br>Issued for the model year · Seats and restraints |
| 18 Aug 2023 | Transport Canada recall 2023468[2]<br>Issued for the model year · Powertrain |
| 20 Nov 2024 | Transport Canada recall 2024709[2]<br>Issued for the model year · Visual system |
| 17 Nov 2025 | Transport Canada recall 2025636[2]<br>Issued for the model year · Other |

| | |
|---|---|
| 31 Aug 2026 | Listed for sale, Montréal, QC[5]<br>Saint-Laurent Hyundai · asking $17,495 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $17,495 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 85 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.