Register entry, as of 29 October 2026 Listed for sale Record ID 4abb301ad5ba

# 2025 Hyundai Elantra SEL Sport

2.0 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KMH | LM4DG | 5 | S | U | 991994 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Hyundai Motor Co | Elantra · 2.0 L | Computes | 2025 | Ulsan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2025 | Engine | 2.0 L, 4 cylinders |
| Make | Hyundai | Fuel | Gasoline |
| Model | Elantra | Drive | Not in the decode |
| Trim | SEL Sport | Maker | HYUNDAI MOTOR CO |
| Body | Sedan | Plant | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/elantra/2025

**2** recalls listed by Transport Canada for this model year

### High voltage

2026235 14 May 2026

Issue: On certain hybrid vehicles, a problem in the hybrid power control unit (HPCU) could cause it to overheat. Note: This problem could cause the vehicle not to start or to enter a reduced power mode and the malfunction indicator lamp to display. Safety Risk: An HPCU that overheats can create a fire risk. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to update the HPCU software.

### Other

2025636 17 Nov 2025

Issue : Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $25,404[5], $1,501 over the median of $23,903[4].

| | |
|---|---|
| Lowest ask | $18,499 |
| Middle half | $22,995 – $24,988 |
| Median ask | $23,903 |
| This car | $25,404 |

Same configuration · 300 live listings · as of 29 Oct 2026

### OTHER 2025 HYUNDAI ELANTRA LISTINGS [5]

| | |
|---|---|
| Kelowna, BC · 7,091 km | $25,908 |
| Kelowna, BC · 37,216 km | $25,704 |
| Kelowna, BC · 22,151 km | $25,408 |
| Kelowna, BC · 51,829 km | $24,704 |
| Kelowna, BC · 36,049 km | $23,504 |
| Victoria, BC · 7,091 km | $25,908 |

## §4 EVENTS

| | |
|---|---|
| 2025 | Model year 2025[1]<br>Assembly plant Ulsan, South Korea |
| 17 Nov 2025 | Transport Canada recall 2025636[2]<br>Issued for the model year · Other |
| 14 May 2026 | Transport Canada recall 2026235[2]<br>Issued for the model year · High voltage |
| 28 Oct 2026 | Listed for sale, Maple Ridge, BC[5]<br>Maple Ridge Hyundai · asking $25,404 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 300 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.