

Register entry, as of 29 October 2026

Listed for sale

Record ID b512c9c71b86

# 2024 Hyundai Elantra SEL

2.0 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**KMH LM4DG 8 R U 664581**

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Elantra · 2.0 L

CHECK 9

Computes

YEAR 10

2024

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |         |        |                    |
|------------|---------|--------|--------------------|
| Model year | 2024    | Engine | 2.0 L, 4 cylinders |
| Make       | Hyundai | Fuel   | Gasoline           |
| Model      | Elantra | Drive  | Not in the decode  |
| Trim       | SEL     | Maker  | HYUNDAI MOTOR CO   |
| Body       | Sedan   | Plant  | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/hyundai/elantra/2024](https://cardog.app/tools/recalls/hyundai/elantra/2024)

## 3 recalls listed by Transport Canada for this model year

### High voltage

2026235 14 May 2026

Issue: On certain hybrid vehicles, a problem in the hybrid power control unit (HPCU) could cause it to overheat. Note: This problem could cause the vehicle not to start or to enter a reduced power mode and the malfunction indicator lamp to display. Safety Risk: An HPCU that overheats can create a fire risk. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to update the HPCU software.

### Other

2025636 17 Nov 2025

Issue: Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

### Engine

2024255 30 Apr 2024

Issue: On certain vehicles, the exhaust gas recirculation (EGR) valve may not have been manufactured properly. As a result, the EGR valve could short circuit and cause a loss of power to the wheels. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to replace the EGR valve.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.

Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.

[www.hyundaicanada.com/en/owners-section/recalls](https://www.hyundaicanada.com/en/owners-section/recalls)



United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE <sup>[4]</sup>

This car asks \$21,882<sup>[5]</sup>, \$117 under the median of \$21,999<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$15,999            |
| Middle half | \$20,995 – \$22,999 |
| Median ask  | \$21,999            |
| This car    | \$21,882            |

Same configuration · 129 live listings · as of 29 Oct 2026

#### OTHER 2024 HYUNDAI ELANTRA LISTINGS <sup>[5]</sup>

|                            |          |
|----------------------------|----------|
| Montréal, QC · 84,809 km   | \$20,995 |
| Victoria, BC · 64,790 km   | \$24,408 |
| Victoria, BC · 36,966 km   | \$23,908 |
| Blainville, QC · 44,388 km | \$23,987 |
| Blainville, QC · 20,948 km | \$24,987 |
| Edmonton, AB · 82,155 km   | \$26,449 |

### §4 EVENTS

|             |                                                                                            |
|-------------|--------------------------------------------------------------------------------------------|
| 2024        | Model year 2024 <sup>[1]</sup><br>Assembly plant Ulsan, South Korea                        |
| 30 Apr 2024 | Transport Canada recall 2024255 <sup>[2]</sup><br>Issued for the model year · Engine       |
| 17 Nov 2025 | Transport Canada recall 2025636 <sup>[2]</sup><br>Issued for the model year · Other        |
| 14 May 2026 | Transport Canada recall 2026235 <sup>[2]</sup><br>Issued for the model year · High voltage |
| 25 Sep 2026 | Listed for sale, Woodstock, ON <sup>[5]</sup><br>Woodstock Hyundai · asking \$21,882       |
| 29 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$21,882                                     |

### §5 DOCUMENTS

Window sticker      We have not collected this label yet.



---

**SOURCES**

- |                                                                     |                                                                                   |
|---------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 129 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                                   |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026                      |

---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

