Register entry, as of 29 October 2026 Listed for sale Record ID 62c6e39ab04e

2022 Hyundai Elantra Limited

1.6 L, 4 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH	LN4AJ	4	N	U	026397
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Hyundai Motor Co	Elantra · 1.6 L	Computes	2022	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	1.6 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Elantra	Drive	FWD
Trim	Limited	Maker	HYUNDAI MOTOR CO
Body	Sedan	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/elantra/2022

8 recalls listed by Transport Canada for this model year

Other

2025636 17 Nov 2025

Issue : Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

Visual system

2024709 20 Nov 2024

Issue: On certain vehicles, the rearview camera may not have been manufactured properly. Over time, the camera could fail and cause the rearview camera image not to display. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: For the Santa Fe model, this recall affects both Santa Fe and Santa Fe Hybrid models. For the Elantra model, this recall affects both Elantra and Elantra Hybrid models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to replace the rearview camera.

Fuel system

2024403 11 Jul 2024

Issue: On certain vehicles, the high-pressure fuel pump could fail. If this happens, the engine may run rough and the check engine light may turn on. This could also cause a sudden loss of engine power while driving. Note: For the Elantra, Kona and Veloster models, this recall only affects the N performance versions. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to update the engine control module software. The high-pressure fuel pump will be replaced, if necessary.

Powertrain

2023468 18 Aug 2023

Issue: On certain Elantra hybrid models, the vehicle could slowly accelerate after the brake pedal is released. Note: This problem can only happen under certain conditions after the vehicle enters "fail-safe" mode. Safety Risk: A vehicle that accelerates on its own could create the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to update the motor control unit (MCU) software.

Powertrain

2022568 6 Oct 2022

Issue: On certain vehicles, a fault in the transmission oil pump can cause the vehicle to enter "fail-safe mode". When this happens, a programming error can cause a sudden loss of power to the wheels after 20-30 seconds. Note: This recall only affects certain vehicles equipped with an 8-speed dual-clutch transmission (DCT). Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, replace the transmission. The dealer will also update the transmission control unit software.

Airbag

2022471 18 Aug 2022

Issue: On certain vehicles, the plastic emblem on the steering wheel airbag cover could detach and become a projectile when the airbag inflates in a crash. Safety Risk: Projectiles in the occupant compartment could increase the risk of an injury. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealership to replace the steering wheel airbag.

2 more on the model-year record, cardog.app/tools/recalls/hyundai/elantra/2022

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $21,995[5], $3,245 over the median of $18,750[4].

Lowest ask	$9,999
Middle half	$16,994 – $20,842
Median ask	$18,750
This car	$21,995

Same model year · 155 live listings · as of 29 Oct 2026

OTHER 2022 HYUNDAI ELANTRA LISTINGS [5]

Kelowna, BC · 99,327 km	$24,733
Dieppe, NB · 95,499 km	$18,998
Guelph, ON · 17,594 km	$18,452
Ottawa, ON · 53,694 km	$19,495
Victoria, BC · 99,327 km	$24,733
Mirabel, QC · 129,538 km	$14,892

§4 EVENTS

2022 Model year 2022[1]
Assembly plant Ulsan, South Korea

4 Mar 2022	Transport Canada recall 2022098[2] Issued for the model year · Seats and restraints
19 May 2022	Transport Canada recall 2022259[2] Issued for the model year · Seats and restraints
18 Aug 2022	Transport Canada recall 2022471[2] Issued for the model year · Airbag
6 Oct 2022	Transport Canada recall 2022568[2] Issued for the model year · Powertrain
18 Aug 2023	Transport Canada recall 2023468[2] Issued for the model year · Powertrain
11 Jul 2024	Transport Canada recall 2024403[2] Issued for the model year · Fuel system
20 Nov 2024	Transport Canada recall 2024709[2] Issued for the model year · Visual system
17 Nov 2025	Transport Canada recall 2025636[2] Issued for the model year · Other
25 Oct 2026	Listed for sale, Oshawa, ON[5] True North Automobiles · asking $21,995
28 Oct 2026	Listing last updated[5] asking $21,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 155 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.