Register entry, as of 27 November 2026 Listed for sale Record ID 692851f2882c

2022 Hyundai Venue SE

1.6 L, 4 cylinders · FWD · Wagon · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH	RB8A3	1	N	U	156147
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai Motor Co	Venue · 1.6 L	Computes	2022	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	1.6 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Venue	Drive	FWD
Trim	SE	Maker	HYUNDAI MOTOR CO
Body	Wagon	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/venue/2022

4 recalls listed by Transport Canada for this model year

Other

2025636 17 Nov 2025

Issue : Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Seats and restraints

2022342 27 Jun 2022

Issue: On certain vehicles, there may be a problem with the driver and front passenger seat belt pretensioners. As a result, the seat belt pretensioners could explode in a crash. If this happens, small pieces of metal could hit people in the vehicle. Note: This recall replaces recall R0200 (Transport Canada Recall No. 2021-627) for Venue models. Vehicles that were repaired under that recall also require this repair. Safety Risk: A seat belt pretensioner that explodes could create a risk of injury. Corrective Actions: Hyundai will notify owners by mail and instruct you to bring your vehicle to a dealership to install protective caps over the driver and front passenger's seat belt pretensioners.

Powertrain 2021534 26 Aug 2021

Issue: Certain vehicles were built with the wrong center console cover. As a result, there is a button for the shift lock release instead of a cover over it. If the button is pushed, the transmission can be shifted out of PARK without a key in the ignition and without pressing the brake pedal. If this happens, and the parking brake is not applied, the vehicle could roll away. Canadian regulations require the shift lock release to be covered. Safety Risk: A parked vehicle that moves unexpectedly could increase the risk of an injury or a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the shift lock release button with a cover.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
www.hyundaicanada.com/en/owners-section/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $16,956[5], $34 under the median of $16,990[4].



Lowest ask	$12,495
Middle half	$15,745 – $17,948
Median ask	$16,990
This car	$16,956

Same configuration · 19 live listings · as of 27 Nov 2026

OTHER 2022 HYUNDAI VENUE LISTINGS [5]

Moncton, NB · 39,233 km	$19,576
Montréal, QC · 65,000 km	$17,744
Laval, QC · 129,593 km	$13,495
Sherbrooke, QC · 38,229 km	$17,395
Saint-Félicien, QC · 62,147 km	$17,995
Guelph, ON · 174,864 km	$14,498

§4 EVENTS

2022	Model year 2022[1] Assembly plant Ulsan, South Korea
26 Aug 2021	Transport Canada recall 2021534[2] Issued for the model year · Powertrain
27 Jun 2022	Transport Canada recall 2022342[2] Issued for the model year · Seats and restraints
23 Sep 2024	Transport Canada recall 2024552[2] Issued for the model year · Label
17 Nov 2025	Transport Canada recall 2025636[2] Issued for the model year · Other

24 Nov 2026	Listed for sale, Val-David, QC[5] Hyundai Ste-Agathe · asking $16,956
27 Nov 2026	Listing last updated[5] asking $16,956

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 19 live listings, as of 27 Nov 2026

[5] Live public dealer listings on Cardog, as of 27 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.