Register entry, as of 28 October 2026 Listed for sale Record ID a24ec4924ac6

2015 Hyundai Veloster GLS(Middle)

1.6 L, 4 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMH	TC6AD	6	F	U	220846
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Hyundai Motor Co	Veloster · 1.6 L	Computes	2015	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	1.6 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Veloster	Drive	Not in the decode
Trim	GLS(Middle)	Maker	HYUNDAI MOTOR CO
Body	Coupe	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/veloster/2015

4 recalls listed by Transport Canada for this model year

Brakes — 2024080 — 8 Feb 2024

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Note: This recall replaces recall R0246 (Transport Canada recall number 2023-527). For the Sonata model, only the Sonata Hybrid model is affected by this recall. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes — 2023125 — 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

Engine — 2021674 — 4 Nov 2021

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects Santa Fe models equipped with a 2.4 L MPI engine, and Veloster models with a 1.6 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

Engine

2020592 2 Dec 2020

Issue: On certain vehicles equipped with a 1.6 L GDI, 2.0 L GDI, or 2.4 L MPI engine, the connecting rod bearings could wear prematurely. As a result, there could be an abnormal knocking noise from the engine and/or the oil pressure warning light may turn on. If you continue to drive the vehicle with worn connecting rod bearings, the engine could fail. An engine failure would cause a sudden loss of power with an inability to restart. In some cases, a damaged connecting rod could puncture the engine block and cause an oil leak. Note: For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this recall. Additional Note: Engine compartment fires can happen for many different reasons. In some cases, there is too much damage to find the cause of a fire. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Oil that leaks onto a hot component could cause a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer for an engine inspection test, to determine if there is bearing damage. If damage is found, the engine will be replaced. Dealers will also update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
www.hyundaicanada.com/en/owners-section/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $8,990[5], the median[4].

Lowest ask	$4,997
Middle half	$7,560 – $10,245
Median ask	$8,990
This car	$8,990

Same model year · 8 live listings · as of 28 Oct 2026

OTHER 2015 HYUNDAI VELOSTER LISTINGS [5]

Chambly, QC · 103,594 km	$10,999
Vaudreuil-Dorion, QC · 207,500 km	$6,990
Ottawa, ON · 212,593 km	$4,997
Calgary, AB · 120,985 km	$9,995
London, ON · 169,981 km	$10,995
Kelowna, BC · 138,511 km	$7,750

§4 EVENTS

2015	Model year 2015[1] Assembly plant Ulsan, South Korea
2 Dec 2020	Transport Canada recall 2020592[2] Issued for the model year · Engine
4 Nov 2021	Transport Canada recall 2021674[2] Issued for the model year · Engine
8 Mar 2023	Transport Canada recall 2023125[2] Issued for the model year · Brakes

8 Feb 2024	Transport Canada recall 2024080[2] Issued for the model year · Brakes
26 Oct 2026	Listed for sale, Gloucester, ON[5] Habes Motors · asking $8,990
28 Oct 2026	Listing last updated[5] asking $8,990

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 8 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.