

Register entry, as of 27 October 2026

Listed for sale

Record ID 5cbf29345fcb

2019 Genesis G70 2.0T Elite, 3.3T Prestige, 3.3T Sport, 3.3T Dynamic Edition, 3.3T Design Edition

2.0 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMT G34LA X K U 016320

WMI 1-3

Genesis · HYUNDAI MOTO...

DESCRIPTOR 4-8

G70 · 2.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.0 L, 4 cylinders
Make	Genesis	Fuel	Gasoline
Model	G70	Drive	Not in the decode
Trim	2.0T Elite, 3.3T Prestige, 3.3T Sport, 3.3T Dynamic Edition, 3.3T Design Edition	Maker	HYUNDAI MOTOR CO
Body	Sedan	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/genesis/g70/2019

5 recalls listed by Transport Canada for this model year

Fuel system 2024403 11 Jul 2024

Issue: On certain vehicles, the high-pressure fuel pump could fail. If this happens, the engine may run rough and the check engine light may turn on. This could also cause a sudden loss of engine power while driving. Note: For the Elantra, Kona and Veloster models, this recall only affects the N performance versions. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to update the engine control module software. The high-pressure fuel pump will be replaced, if necessary.

Engine 2024158 8 Mar 2024

Issue: Under certain conditions, the left turbocharger oil feed pipe and hose assembly could become damaged. If this happens, oil could leak onto hot components. Note: This recall only affects vehicles equipped with a 3.3 L turbo (T-GDI) engine. This recall replaces recall R0159 (Transport Canada recall number 2019-350). Vehicles that were repaired under that recall also require this repair. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the left turbocharger oil feed pipe and hose assembly.



Electrical

2024089 13 Feb 2024

Issue: Under certain conditions, water could leak into the starter solenoid. If this happens, the solenoid could short circuit. Safety Risk: A short circuit can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to install an updated relay in the engine junction box. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Structure

2022143 28 Mar 2022

Issue: On certain vehicles, a part in the trunk release latch could fail. If this happens, the emergency trunk release located inside the trunk compartment may not work properly. This could prevent a person that is trapped inside the trunk from opening it. Safety Risk: If a person is closed inside the trunk compartment, they may not be able to get out. This could create a risk of injury. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to inspect trunk latch and, if necessary, replace the trunk latch base.

Brakes

2021134 10 Mar 2021

Issue: On certain vehicles, a problem in the control module for the antilock brake system (ABS) could cause it to short circuit. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to replace fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Listed for the model year, not checked against your VIN. Genesis confirms which apply.

Check your VIN with Genesis Canada or call a Genesis dealer with your VIN.

acquisition.genesis.ca/en/recalls-lookup

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$15,995^[5], \$4,604 under the median of \$20,599^[4].



Lowest ask	\$15,995
Middle half	\$19,995 – \$22,490
Median ask	\$20,599
This car	\$15,995

Same model year · 9 live listings · as of 27 Oct 2026

OTHER 2019 GENESIS G70 LISTINGS ^[5]

Brampton, ON · 111,658 km	\$20,888
Richmond Hill, ON · 100,022 km	\$19,995
Southwold, ON · 88,684 km	\$20,599
Laval, QC · 72,814 km	\$25,995
Toronto, ON · 106,649 km	\$18,995
Aurora, ON · 67,513 km	\$22,490

§4 EVENTS

2019

Model year 2019^[1]

Assembly plant Ulsan, South Korea



10 Mar 2021	Transport Canada recall 2021134 ^[2] Issued for the model year · Brakes
28 Mar 2022	Transport Canada recall 2022143 ^[2] Issued for the model year · Structure
13 Feb 2024	Transport Canada recall 2024089 ^[2] Issued for the model year · Electrical
8 Mar 2024	Transport Canada recall 2024158 ^[2] Issued for the model year · Engine
11 Jul 2024	Transport Canada recall 2024403 ^[2] Issued for the model year · Fuel system
20 May 2026	Listed for sale, North York, ON ^[5] CAR CONNECTION TORONTO · asking \$15,995
27 Oct 2026	Listing last updated ^[5] asking \$15,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 9 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

