Register entry, as of 29 November 2026 Listed for sale Record ID e56d3e72922c

2021 Genesis G70 3.3T Sport Advanced (AWD/RWD); 3.3T Sport Prestige (AWD/RWD)

3.3 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMT	G54LE	8	M	U	076466
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Genesis · HYUNDAI MOTO…	G70 · 3.3 L	Computes	2021	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.3 L, 6 cylinders
Make	Genesis	Fuel	Gasoline
Model	G70	Drive	Not in the decode
Trim	3.3T Sport Advanced (AWD/RWD); 3.3T Sport Prestige (AWD/RWD)	Maker	HYUNDAI MOTOR CO
Body	Sedan	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/genesis/g70/2021

4 recalls listed by Transport Canada for this model year

Fuel system

2024403 11 Jul 2024

Issue: On certain vehicles, the high-pressure fuel pump could fail. If this happens, the engine may run rough and the check engine light may turn on. This could also cause a sudden loss of engine power while driving. Note: For the Elantra, Kona and Veloster models, this recall only affects the N performance versions. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to update the engine control module software. The high-pressure fuel pump will be replaced, if necessary.

Engine

2024158 8 Mar 2024

Issue: Under certain conditions, the left turbocharger oil feed pipe and hose assembly could become damaged. If this happens, oil could leak onto hot components. Note: This recall only affects vehicles equipped with a 3.3 L turbo (T-GDI) engine. This recall replaces recall R0159 (Transport Canada recall number 2019-350). Vehicles that were repaired under that recall also require this repair. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the left turbocharger oil feed pipe and hose assembly.

Brakes

2021134 10 Mar 2021

Issue: On certain vehicles, a problem in the control module for the antilock brake system (ABS) could cause it to short circuit. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to replace fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Fuel system

2020447 21 Sep 2020

Issue: On certain vehicles, there could a problem with the low pressure fuel pump assembly. As a result, the flow of fuel to the engine could be partially blocked. Under certain conditions, this could cause the engine to stall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the jet nozzle of the low pressure fuel pump assembly, and repair it, if necessary.

> Listed for the model year, not checked against your VIN. Genesis confirms which apply.
> Check your VIN with Genesis Canada or call a Genesis dealer with your VIN.
> acquisition.genesis.ca/en/recalls-lookup

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,999[5], $149 over the median of $26,850[4].



Lowest ask	$22,995
Middle half	$25,492 – $28,739
Median ask	$26,850
This car	$26,999

Same model year · 15 live listings · as of 29 Nov 2026

OTHER 2021 GENESIS G70 LISTINGS [5]

Saint-Jean-Sur-Richelieu, QC · 19,358 km	$29,490
Kingston, ON · 89,935 km	$25,995
Cochrane, AB · 27,414 km	$31,888
Regina, SK · 109,179 km	$26,850
Burlington, ON · 59,439 km	$27,988
St. Catharines, ON · 45,735 km	$33,688

§4 EVENTS

2021	Model year 2021[1] Assembly plant Ulsan, South Korea
21 Sep 2020	Transport Canada recall 2020447[2] Issued for the model year · Fuel system
10 Mar 2021	Transport Canada recall 2021134[2] Issued for the model year · Brakes

8 Mar 2024	Transport Canada recall 2024158[2] Issued for the model year · Engine
11 Jul 2024	Transport Canada recall 2024403[2] Issued for the model year · Fuel system
6 Nov 2026	Listed for sale, Markham, ON[5] Markham Honda · asking $26,999
29 Nov 2026	Listing last updated[5] asking $26,999

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 15 live listings, as of 29 Nov 2026

[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.