Register entry, as of 28 October 2026 Listed for sale Record ID f30541937993

# 2023 Genesis GV80 3.5T, 3.5T Advanced, 3.5T Advanced+, 3.5T Prestige

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KMU | HCESC | 9 | P | U | 139722 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Genesis · HYUNDAI MOTO… | GV80 · 3.5 L | Computes | 2023 | Ulsan | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 3.5 L, 6 cylinders |
| Make | Genesis | Fuel | Gasoline |
| Model | GV80 | Drive | 4WD |
| Trim | 3.5T, 3.5T Advanced, 3.5T Advanced+, 3.5T Prestige | Maker | HYUNDAI MOTOR CO |
| Body | Sport Utility Vehicle | Plant | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/genesis/gv80/2023

**6** recalls listed by Transport Canada for this model year

### Fuel system

2026185 9 Apr 2026

Issue: On certain vehicles, the nuts for the crossover fuel pipe may not have been properly tightened. As a result, fuel could leak. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Genesis will notify owners in writing and advise you to take your vehicle to a dealership to inspect and tighten the nuts or replace the crossover high-pressure fuel pipe, as necessary.

### Other

2025636 17 Nov 2025

Issue : Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

### Lights and instruments

2025091 19 Feb 2025

Issue: On certain vehicles, a software problem could cause the instrument panel cluster display(s) not to display properly, or at all when the vehicle is started. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, warning lights and malfunction tell-tales. Note: For the GV70 model, this recall affects both the GV70 and Electrified GV70 (EV) models. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: Genesis will notify owners in writing and advise you to take your vehicle to a dealership to update the instrument panel cluster display software.

### Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

### Fuel system

2024235 19 Apr 2024

Issue: On certain vehicles, the low-pressure fuel pump could fail when the outside temperature is high. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-505. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump.

### Seats and restraints

2023074 17 Feb 2023

Issue: On certain vehicles, there may be a problem with the front seat belt pretensioners. As a result, the driver and/or passenger seat belt pretensioners could explode in a crash. If this happens, small pieces of metal could hit people in the vehicle. Note: This recall replaces recall R0200 (Transport Canada Recall No. 2021-627). Vehicles that were repaired under that recall also require this repair. Safety Risk: A seat belt pretensioner that explodes could create a risk of injury. Corrective Action: Genesis will notify owners by mail and instruct you to bring your vehicle to a dealership to install protective caps over the driver and front passenger's seat belt pretensioners, as necessary.

Listed for the model year, not checked against your VIN. Genesis confirms which apply.
Check your VIN with Genesis Canada or call a Genesis dealer with your VIN.
acquisition.genesis.ca/en/recalls-lookup

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $45,697[5], $2,898 under the median of $48,595[4].

| | |
|---|---|
| Lowest ask | $44,998 |
| Middle half | $46,998 – $49,626 |
| Median ask | $48,595 |
| This car | $45,697 |

Same configuration · 11 live listings · as of 28 Oct 2026

### OTHER 2023 GENESIS GV80 LISTINGS [5]

| | |
|---|---|
| Toronto, ON · 80,128 km | $38,995 |
| Toronto, ON · 80,220 km | $38,888 |
| Brandon, MB · 110,577 km | $45,999 |
| Toronto, ON · 80,220 km | $38,888 |
| Brantford, ON · 87,327 km | $45,086 |
| Toronto, ON · 60,739 km | $47,998 |

## §4 EVENTS

2023 Model year 2023[1]
Assembly plant Ulsan, South Korea

| | |
|---|---|
| 17 Feb 2023 | Transport Canada recall 2023074[2]<br>Issued for the model year · Seats and restraints |
| 19 Apr 2024 | Transport Canada recall 2024235[2]<br>Issued for the model year · Fuel system |
| 23 Sep 2024 | Transport Canada recall 2024552[2]<br>Issued for the model year · Label |
| 19 Feb 2025 | Transport Canada recall 2025091[2]<br>Issued for the model year · Lights and instruments |
| 17 Nov 2025 | Transport Canada recall 2025636[2]<br>Issued for the model year · Other |
| 9 Apr 2026 | Transport Canada recall 2026185[2]<br>Issued for the model year · Fuel system |
| 1 May 2026 | Listed for sale, London, ON[5]<br>Finch Nissan · asking $45,697 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $45,697 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 11 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.