Register entry, as of 28 October 2026 Listed for sale Record ID 28f1cdde3aaf

2025 Genesis GV80 3.5T e-SC Coupe

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMU	JBESC	1	S	U	240752
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Genesis · HYUNDAI MOTO…	GV80 · 3.5 L	Computes	2025	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	3.5 L, 6 cylinders
Make	Genesis	Fuel	Gasoline
Model	GV80	Drive	4WD
Trim	3.5T e-SC Coupe	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/genesis/gv80/2025

5 recalls listed by Transport Canada for this model year

Fuel system

2026185 9 Apr 2026

Issue: On certain vehicles, the nuts for the crossover fuel pipe may not have been properly tightened. As a result, fuel could leak. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Genesis will notify owners in writing and advise you to take your vehicle to a dealership to inspect and tighten the nuts or replace the crossover high-pressure fuel pipe, as necessary.

Lights and instruments

2026008 15 Jan 2026

Issue: On certain vehicles, a software problem could cause the instrument panel cluster and audio/video/navigation displays to reboot while driving. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, warning lights and malfunction tell-tales. Note: For the GV70 model, this recall affects both gas and EV (electric) models. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: To reduce the safety risk, Genesis advises you to disable the HD radio feature while driving until the recall repairs have been completed. Genesis will notify owners in writing and send a wireless over-the-air software update to eligible vehicles to update the audio/video/navigation software. Alternatively, you may schedule an appointment to have the update performed at a Genesis dealership.

Other

2025636 17 Nov 2025

Issue : Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Visual system

2024447 7 Aug 2024

Issue: Under certain conditions, a software problem could cause the rearview camera image not to display. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display properly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: To reduce the safety risk, Genesis advises you to limit the reverse speed to below 10 km/h until the recall repairs are completed. Genesis will notify owners in writing and advise you to take your vehicle to a dealership to update the rearview camera system software.

> Listed for the model year, not checked against your VIN. Genesis confirms which apply.
> Check your VIN with Genesis Canada or call a Genesis dealer with your VIN.
> acquisition.genesis.ca/en/recalls-lookup

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $73,995[5], $4 under the median of $73,999[4].

Lowest ask	$59,980
Middle half	$71,919 – $77,997
Median ask	$73,999
This car	$73,995

Same model year · 15 live listings · as of 28 Oct 2026

OTHER 2025 GENESIS GV80 LISTINGS [5]

Edmonton, AB · 39,438 km	$75,980
Calgary, AB · 0 km	$79,999
Strathmore, AB · 27,440 km	$75,270
Calgary, AB · 39,868 km	$73,999
Calgary, AB · 37,166 km	$70,843
Barrie, ON · 30,544 km	$59,980

§4 EVENTS

2025	Model year 2025[1] Assembly plant Ulsan, South Korea
7 Aug 2024	Transport Canada recall 2024447[2] Issued for the model year · Visual system
23 Sep 2024	Transport Canada recall 2024552[2] Issued for the model year · Label

17 Nov 2025	Transport Canada recall 2025636[2] Issued for the model year · Other
15 Jan 2026	Transport Canada recall 2026008[2] Issued for the model year · Lights and instruments
9 Apr 2026	Transport Canada recall 2026185[2] Issued for the model year · Fuel system
17 Apr 2026	Listed for sale, Brossard, QC[5] Brossard Hyundai · asking $73,995
28 Oct 2026	Listing last updated[5] asking $73,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 15 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.