Register entry, as of 27 October 2026 Listed for sale Record ID 4e0f03541125

2023 Genesis GV60 Advanced

4WD · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

KMU	KCDTC	5	P	U	012996
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Genesis · HYUNDAI MOTO…	GV60	Computes	2023	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	Not in the decode
Make	Genesis	Fuel	Electric
Model	GV60	Drive	4WD
Trim	Advanced	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/genesis/gv60/2023

9 recalls listed by Transport Canada for this model year

Accessories

2025492 18 Sep 2025

Issue: On certain vehicles, the exterior stainless-steel trim above the windshield may not be attached properly. As a result, the trim could loosen and detach from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Genesis will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the exterior stainless-steel trim above the windshield.

Lights and instruments

2025383 17 Jul 2025

Issue: On certain vehicles, a software problem could cause the instrument panel cluster display(s) not to display when the vehicle is started. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, warning lights and malfunction tell-tales. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: Genesis will notify owners in writing and advise you to take your vehicle to a dealership to update the instrument panel cluster display software.

High voltage

2024701 18 Nov 2024

Issue: Over time, the integrated charging control unit (ICCU) could become damaged. As a result, the 12 V battery will not charge and could cause the vehicle to enter a reduced power mode. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels. Note: This recall replaces Transport Canada recall no. 2024-174. Vehicles that were repaired under that recall also require this repair. This problem will cause a warning light to turn on and warning messages to display before any loss of power. For the Genesis GV70 and G80 models, only the electric versions (EV) are affected. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle software. The dealer will also inspect and, if necessary, replace the ICCU and ICCU fuse.

Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Visual system

2024447 7 Aug 2024

Issue: Under certain conditions, a software problem could cause the rearview camera image not to display. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display properly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: To reduce the safety risk, Genesis advises you to limit the reverse speed to below 10 km/h until the recall repairs are completed. Genesis will notify owners in writing and advise you to take your vehicle to a dealership to update the rearview camera system software.

High voltage

2024174 15 Mar 2024

This recall was replaced by Transport Canada recall no. 2024-701. Issue: Over time, the integrated charging control unit (ICCU) could become damaged. As a result, the 12 V battery will not charge and could cause the vehicle to enter a reduced power mode. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels. Note: This problem will cause a warning light to turn on and warning messages to display before any loss of power. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle software. The dealer will also inspect and, if necessary, replace the ICCU and ICCU fuse.

3 more on the model-year record, cardog.app/tools/recalls/genesis/gv60/2023

> Listed for the model year, not checked against your VIN. Genesis confirms which apply.
> Check your VIN with Genesis Canada or call a Genesis dealer with your VIN.
> acquisition.genesis.ca/en/recalls-lookup

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $30,697[5], $12,798 under the median of $43,495[4].



Lowest ask	$30,697
Middle half	$39,170 – $49,495
Median ask	$43,495
This car	$30,697

Same model year · 4 live listings · as of 27 Oct 2026

OTHER 2023 GENESIS GV60 LISTINGS [5]

Brossard, QC · 89,269 km	$41,995
Brossard, QC · 53,125 km	$44,995
Weyburn, SK · 2,255 km	$62,995
Esterhazy, SK · 2,255 km	$62,995

§4 EVENTS

2023	Model year 2023[1] Assembly plant Ulsan, South Korea
17 Feb 2023	Transport Canada recall 2023074[2] Issued for the model year · Seats and restraints
26 Apr 2023	Transport Canada recall 2023252[2] Issued for the model year · Powertrain
4 Aug 2023	Transport Canada recall 2023438[2] Issued for the model year · Seats and restraints
15 Mar 2024	Transport Canada recall 2024174[2] Issued for the model year · High voltage
7 Aug 2024	Transport Canada recall 2024447[2] Issued for the model year · Visual system
23 Sep 2024	Transport Canada recall 2024552[2] Issued for the model year · Label
18 Nov 2024	Transport Canada recall 2024701[2] Issued for the model year · High voltage
17 Jul 2025	Transport Canada recall 2025383[2] Issued for the model year · Lights and instruments
18 Sep 2025	Transport Canada recall 2025492[2] Issued for the model year · Accessories
26 Oct 2026	Listed for sale, London, ON[5] Finch Nissan · asking $30,697

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 4 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.