Register entry, as of 28 October 2026 Listed for sale Record ID 4d71f4bb4d3a

2023 Genesis GV70 2.5T, 2.5T Select, 2.5T Advanced, 2.5T Sport Prestige

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMU	MADTB	5	P	U	119343
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Genesis · HYUNDAI MOTO…	GV70 · 2.5 L	Computes	2023	Ulsan	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	2.5 L, 4 cylinders
Make	Genesis	Fuel	Gasoline
Model	GV70	Drive	4WD
Trim	2.5T, 2.5T Select, 2.5T Advanced, 2.5T Sport Prestige	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/genesis/gv70/2023

6 recalls listed by Transport Canada for this model year

Fuel system

2026185 9 Apr 2026

Issue: On certain vehicles, the nuts for the crossover fuel pipe may not have been properly tightened. As a result, fuel could leak. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Genesis will notify owners in writing and advise you to take your vehicle to a dealership to inspect and tighten the nuts or replace the crossover high-pressure fuel pipe, as necessary.

High voltage

2024701 18 Nov 2024

Issue: Over time, the integrated charging control unit (ICCU) could become damaged. As a result, the 12 V battery will not charge and could cause the vehicle to enter a reduced power mode. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels. Note: This recall replaces Transport Canada recall no. 2024-174. Vehicles that were repaired under that recall also require this repair. This problem will cause a warning light to turn on and warning messages to display before any loss of power. For the Genesis GV70 and G80 models, only the electric versions (EV) are affected. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle software. The dealer will also inspect and, if necessary, replace the ICCU and ICCU fuse.

Label
2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Fuel system
2024235 19 Apr 2024

Issue: On certain vehicles, the low-pressure fuel pump could fail when the outside temperature is high. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-505. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump.

High voltage
2024174 15 Mar 2024

This recall was replaced by Transport Canada recall no. 2024-701. Issue: Over time, the integrated charging control unit (ICCU) could become damaged. As a result, the 12 V battery will not charge and could cause the vehicle to enter a reduced power mode. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels. Note: This problem will cause a warning light to turn on and warning messages to display before any loss of power. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle software. The dealer will also inspect and, if necessary, replace the ICCU and ICCU fuse.

Seats and restraints
2023074 17 Feb 2023

Issue: On certain vehicles, there may be a problem with the front seat belt pretensioners. As a result, the driver and/or passenger seat belt pretensioners could explode in a crash. If this happens, small pieces of metal could hit people in the vehicle. Note: This recall replaces recall R0200 (Transport Canada Recall No. 2021-627). Vehicles that were repaired under that recall also require this repair. Safety Risk: A seat belt pretensioner that explodes could create a risk of injury. Corrective Action: Genesis will notify owners by mail and instruct you to bring your vehicle to a dealership to install protective caps over the driver and front passenger's seat belt pretensioners, as necessary.

> Listed for the model year, not checked against your VIN. Genesis confirms which apply.
> Check your VIN with Genesis Canada or call a Genesis dealer with your VIN.
> acquisition.genesis.ca/en/recalls-lookup

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $39,788[5], $395 over the median of $39,393[4].



Lowest ask	$33,888
Middle half	$38,560 – $42,860
Median ask	$39,393
This car	$39,788

Same configuration · 18 live listings · as of 28 Oct 2026

OTHER 2023 GENESIS GV70 LISTINGS [5]

Laval, QC · 28,818 km	$40,180
Markham, ON · 38,351 km	$41,021
Toronto, ON · 64,696 km	$38,998
Toronto, ON · 85,389 km	$35,998
Toronto, ON · 68,870 km	$48,998
Toronto, ON · 66,877 km	$45,998

§4 EVENTS

2023	Model year 2023[1] Assembly plant Ulsan, South Korea
17 Feb 2023	Transport Canada recall 2023074[2] Issued for the model year · Seats and restraints
15 Mar 2024	Transport Canada recall 2024174[2] Issued for the model year · High voltage
19 Apr 2024	Transport Canada recall 2024235[2] Issued for the model year · Fuel system
23 Sep 2024	Transport Canada recall 2024552[2] Issued for the model year · Label
18 Nov 2024	Transport Canada recall 2024701[2] Issued for the model year · High voltage
9 Apr 2026	Transport Canada recall 2026185[2] Issued for the model year · Fuel system
26 Oct 2026	Listed for sale, Markham, ON[5] Don Valley North Lexus · asking $39,788
28 Oct 2026	Listing last updated[5] asking $39,788

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 18 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.