

Register entry, as of 27 October 2026

Listed for sale

Record ID 09e631c3a1f4

2022 Genesis GV70 3.5T, 3.5T Sport Advanced, 3.5T Sport Prestige

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KMU **MCDTC** **1** **N** **U** **015657**

WMI 1-3

Genesis · HYUNDAI MOTO...

DESCRIPTOR 4-8

GV70 · 3.5 L

CHECK 9

Computes

YEAR 10

2022

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	3.5 L, 6 cylinders
Make	Genesis	Fuel	Gasoline
Model	GV70	Drive	4WD
Trim	3.5T, 3.5T Sport Advanced, 3.5T Sport Prestige	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/genesis/gv70/2022

6 recalls listed by Transport Canada for this model year

Fuel system 2026185 9 Apr 2026

Issue: On certain vehicles, the nuts for the crossover fuel pipe may not have been properly tightened. As a result, fuel could leak. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Genesis will notify owners in writing and advise you to take your vehicle to a dealership to inspect and tighten the nuts or replace the crossover high-pressure fuel pipe, as necessary.

Label 2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Fuel system 2024235 19 Apr 2024

Issue: On certain vehicles, the low-pressure fuel pump could fail when the outside temperature is high. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-505. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump.



Fuel system

2023505 12 Sep 2023

This recall was replaced by Transport Canada recall no. 2024-235. Issue: On certain vehicles, the low-pressure fuel pump could fail when the outside temperature is high. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump.

Seats and restraints

2023074 17 Feb 2023

Issue: On certain vehicles, there may be a problem with the front seat belt pretensioners. As a result, the driver and/or passenger seat belt pretensioners could explode in a crash. If this happens, small pieces of metal could hit people in the vehicle. Note: This recall replaces recall R0200 (Transport Canada Recall No. 2021-627). Vehicles that were repaired under that recall also require this repair. Safety Risk: A seat belt pretensioner that explodes could create a risk of injury. Corrective Action: Genesis will notify owners by mail and instruct you to bring your vehicle to a dealership to install protective caps over the driver and front passenger's seat belt pretensioners, as necessary.

Seats and restraints

2021627 13 Oct 2021

This recall was replaced by Transport Canada Recall No. 2023-074. Issue: On certain vehicles, there may be a problem with the front seat belt pretensioners. As a result, the driver and/or passenger seat belt pretensioners could explode in a crash. If this happens, small pieces of metal could hit people in the vehicle. Safety Risk: A seat belt pretensioner that explodes could create a risk of injury. Corrective Action: Genesis will notify owners by mail and instruct you to bring your vehicle to a dealer to replace the driver's and/or passenger's front seat belt pretensioners, as necessary.

Listed for the model year, not checked against your VIN. Genesis confirms which apply.

Check your VIN with Genesis Canada or call a Genesis dealer with your VIN.

acquisition.genesis.ca/en/recalls-lookup

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$43,991^[5], \$4,103 over the median of \$39,888^[4].



Lowest ask	\$32,490
Middle half	\$35,903 – \$42,182
Median ask	\$39,888
This car	\$43,991

Same configuration · 19 live listings · as of 27 Oct 2026

OTHER 2022 GENESIS GV70 LISTINGS ^[5]

Smiths Falls, ON · 87,334 km	\$34,998
Ottawa, ON · 89,990 km	\$70,210
Markham, ON · 44,525 km	\$36,688
Saint-Basile-Le-Grand, QC · 46,743 km	\$34,989
Saint-Basile-Le-Grand, QC · 124,713 km	\$32,988
Sherwood Park, AB · 91,991 km	\$40,906

§4 EVENTS

2022 Model year 2022^[1]
Assembly plant Ulsan, South Korea



13 Oct 2021	Transport Canada recall 2021627 ^[2] Issued for the model year · Seats and restraints
17 Feb 2023	Transport Canada recall 2023074 ^[2] Issued for the model year · Seats and restraints
12 Sep 2023	Transport Canada recall 2023505 ^[2] Issued for the model year · Fuel system
19 Apr 2024	Transport Canada recall 2024235 ^[2] Issued for the model year · Fuel system
23 Sep 2024	Transport Canada recall 2024552 ^[2] Issued for the model year · Label
9 Apr 2026	Transport Canada recall 2026185 ^[2] Issued for the model year · Fuel system
26 Oct 2026	Listed for sale, Calgary, AB ^[5] Country Hills Hyundai · asking \$43,991
27 Oct 2026	Listing last updated ^[5] asking \$43,991

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 19 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

