Register entry, as of 29 October 2026 Listed for sale Record ID 06b373036c35

2012 Kia Rondo GLS

2.4 L · Wagon · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KNA	HH8A8	1	C	7	394437
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Corporation	Rondo · 2.4 L	Computes	2012	Gwangju	Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	2.4 L
Make	Kia	Fuel	Gasoline
Model	Rondo	Drive	Not in the decode
Trim	GLS	Maker	KIA CORPORATION
Body	Wagon	Plant	Gwangju, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/rondo/2012

3 recalls listed by Transport Canada for this model year

Brakes

2023529 26 Sep 2023

Issue: On certain vehicles, the brake hydraulic electronic control unit (HECU) could short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse(s) for the HECU. Kia recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Engine

2021040 1 Feb 2021

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure could cause a sudden loss of power with an inability to restart. Note: This only affects vehicles equipped with a 2.4 L MPI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Kia will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Kia recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Kia advises you to immediately visit a Kia dealership to have your vehicle diagnosed.

Brakes

2013098 3 Apr 2013

On certain vehicles, the stop lamp switch may fail and cause intermittent operation of the brake lights. Failure of the brake lights to illuminate when the brake pedal is depressed could result in a crash causing property damage and/or personal injury. Correction: Dealers will replace the switch.

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

§3 VALUE [3]

This car asks $5,995[4], $1,045 over the median of $4,950[3].



Lowest ask	$3,950
Middle half	$4,450 – $5,472
Median ask	$4,950
This car	$5,995

Same model year · 3 live listings · as of 29 Oct 2026

OTHER 2012 KIA RONDO LISTINGS [4]

Charlesbourg, QC · 120,101 km	$4,950
Charlesbourg, QC · 202,675 km	$3,950

§4 EVENTS

2012	Model year 2012[1] Assembly plant Gwangju, South Korea
3 Apr 2013	Transport Canada recall 2013098[2] Issued for the model year · Brakes
1 Feb 2021	Transport Canada recall 2021040[2] Issued for the model year · Engine
26 Sep 2023	Transport Canada recall 2023529[2] Issued for the model year · Brakes
25 Oct 2026	Listed for sale, Mirabel, QC[4] Auto Studio 72 · asking $5,995
29 Oct 2026	Listing last updated[4] asking $5,995

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 3 live listings, as of 29 Oct 2026

[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.