Register entry, as of 28 November 2026 Listed for sale Record ID f218547170d4

# 2023 Kia Seltos EX

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KND | ERCAA | 4 | P | 7 | 424643 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Kia Corporation | Seltos · 2.0 L | Computes | 2023 | Gwang-Ju | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 2.0 L, 4 cylinders |
| Make | Kia | Fuel | Gasoline |
| Model | Seltos | Drive | AWD |
| Trim | EX | Maker | KIA CORPORATION |
| Body | Sport Utility Vehicle | Plant | Gwang-Ju, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/seltos/2023

**4** recalls listed by Transport Canada for this model year

### Engine

2025083 18 Feb 2025

Issue: On certain vehicles, the piston oil rings may not have been manufactured properly and could damage the cylinder walls. As a result, the engine could make abnormal noises, and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This recall only affects certain vehicles equipped with a 2.0L MPI engine. Safety Risk: An engine failure could cause a sudden loss of power to the wheels and/or increase the risk of a vehicle fire. Both issues could increase the risk of a crash or injury. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the engine. The dealer will also install a software that will monitor the engine and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the engine.

### Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

### Electrical

2024093 14 Feb 2024

Issue: On certain vehicles, the 4WD control unit under the driver's seat may become contaminated by a mixture of salt and moisture inside the vehicle. Over time, this can lead to corrosion that could cause a short circuit. Note: This recall only affects vehicles equipped with all-wheel drive. Safety Risk: A short circuit can create a fire risk, even while the vehicle is parked and turned off. Corrective actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the 4WD control unit. The control unit and other components will be replaced as necessary. The dealer will also install a protective cover over the 4WD control unit. Kia advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Powertrain 2023421 1 Aug 2023

Issue: On certain vehicles, the circuit board in the electric oil pump assembly for the transmission may be damaged. As a result, the circuit board could short circuit and overheat. Safety Risk: A short circuit could create the risk of a fire. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the transmission electric oil pump assembly, and replace it as necessary. Kia recommends parking your vehicle outside and away from other vehicles or buildings until the recall repairs are completed.

Listed for the model year, not checked against your VIN. Kia confirms which apply.
Check your VIN with Kia Canada or call a Kia dealer with your VIN.
www.kia.ca/en/owners/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $24,488[5], $7 over the median of $24,481[4].




| | |
|---|---|
| Lowest ask | $19,495 |
| Middle half | $22,865 – $25,396 |
| Median ask | $24,481 |
| This car | $24,488 |

Same configuration · 36 live listings · as of 28 Nov 2026

### OTHER 2023 KIA SELTOS LISTINGS [5]

| | |
|---|---|
| Laval, QC · 159,825 km | $17,495 |
| Saint-Hyacinthe, QC · 59,200 km | $22,995 |
| Surrey, BC · 82,600 km | $18,885 |
| Laval, QC · 44,783 km | $23,995 |
| Pointe-Claire, QC · 78,855 km | $22,474 |
| Québec, QC · 53,127 km | $24,589 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant Gwang-Ju, South Korea |
| 1 Aug 2023 | Transport Canada recall 2023421[2]<br>Issued for the model year · Powertrain |
| 14 Feb 2024 | Transport Canada recall 2024093[2]<br>Issued for the model year · Electrical |
| 15 Aug 2024 | Transport Canada recall 2024549[2]<br>Issued for the model year · Label |
| 18 Feb 2025 | Transport Canada recall 2025083[2]<br>Issued for the model year · Engine |

| | | |
|---|---|---|
| 24 Nov 2026 | Listed for sale, Rivière-du-Loup, QC[5]<br>Rivière-du-Loup Mitsubishi · asking $24,488 |
| 28 Nov 2026 | Listing last updated[5]<br>asking $24,488 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 36 live listings, as of 28 Nov 2026

[5] Live public dealer listings on Cardog, as of 28 Nov 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.